

Smart Structures
Professor Mohammed Rabius Sunny
Department of Aerospace Engineering
Indian Institute of Technology, Kharagpur
Week - 08
Lecture No – 42

Temperature and Stress Dependent Phase Transformation Modeling

In the last lecture we saw a basic introduction to shape memory alloys. We saw the different phases austenite and martensite and we saw how this phase transformation leads to shape memory effect. Now, today we look into the phase transition temperatures and the corresponding mathematical formulation. Now, to do this we define a variable called x_i and this denotes martensite fraction. What it means is when x_i is equal to 1 the material is fully martensite x_i is equal to 0 means it is austenite and when x_i is between 0 and 1 this means partially martensite and partially austenite. So, when phase transition takes place if it transits to an austenite phase x_i becomes 0 if it transits to a martensite phase x_i becomes 1 and this entire variation of this x_i can be shown by a graph like this.


So, all this phase transformation can be seen as a variation of x_i and if we say that the transition is happening through temperature that means, how x_i is varying with time and this kind of variation is shown by a graph like this. Now, here are some key points this we call M_f this we call M_s and here we call it A_f and we call this as A_s ok. So, there is one error in the diagram we have. So, this is x_i and this is temperature x_i is varying with temperature now here x_i is equal to 1.

Now this diagram when the temperature increases follow a path follows this path and when the temperature decreases it follows this path it means suppose I have a material at temperature beyond A_f . So, in this region maybe here the martensite fraction is 0 which means the material is entirely austenite. Now if I reduce the temperature then while reducing it will follow this arrow. So, it will follow this path. So, till it comes to M_s it will maintain x_i is equal to 0 which means there is still it is still fully austenite there is no phase transformation.

Now, when it crosses M_s and if we further reduce the temperature x_i starts growing up and gradually it becomes 1 when the temperature is M_f . So, from M_s to M_f there is a variation of x_i and starting from 0 it becomes 1 when it reaches M_f . If I further cool it down it will maintain x_i equal to 1 which means below M_f the material is fully martensite. Now if we start increasing the temperature it will not follow this path it will follow this path which is shown by the arrow pointing towards the right side. And till A_s which we called austenite start temperature x_i will be maintained will be maintaining a value of 1 and after A_s the value will reduce and it will become 0 when it reaches A_f .

So, here we have now 4 quantities A_s and that is called austenite start temperature and we have A_f and that we called austenite finish temperature and then we have M_s what is that is called martensite start temperature and then we have M_f and that is called martensite finish temperature. Now this behavior as we can see that the when temperature increases it follows a certain path when temperature reduces it follows a certain path. So, it is a path dependent behavior. So, to know the amount of martensite quantity present the martensite fraction just knowing the temperature is not sufficient. For example, if somebody tells me that the value of the present temperature is between M_s and A_s then if it is here, it can x_i can be 0 if it is here x_i can be 1 and that depends on what the temperature was before.

(Refer slide time: 8:46)



So, if the temperature was more than A_f before and it has been cooled down to this temperature which is between M_s and A_s then we can say that x_i is 0. On the other hand, if the initial temperature was if the initial temperature was less than M_f and it is heated up to a temperature which is between M_s and A_s then x_i is equal to 1. So, it is here. So, it is path dependent it is history dependent and it is historic. So, it is a path or history dependent behavior and it shows hysteresis and this is martensite fraction versus temperature behavior.

Now, we will try to fit some equation here and again we can see that this part of the graph it is just a constant. So, here x_i is independent of temperature till A_s in this part of the graph again it is constant x_i is equal to 0 which is that is at M_s and beyond whereas, this part between M_s and A_s and this part between M_s and A_s and A_f . So, this part between M_s and A M_f and this part between A_s and A_f they show some curve variation and we

need to mathematically model that. So, to do that so, there are different types of curves that has been fitted to it here we will talk about a curve that is that is based on cosine function. So, what we do is we consider xi to be a function like this.

$$\xi = C_1 \cos \alpha_M (T - M_f) + C_2$$

$$T = M_s$$

$$\Rightarrow 0 = C_1 \cos \alpha_M (M_s - M_f) + C_2$$

$$\alpha_M = \frac{\pi}{M_s - M_f}$$

$$T = M_f$$

$$\rightarrow 1 = C_1 + C_2$$

$$C_1 = C_2 = \frac{1}{2}$$

$$\xi = \frac{1}{2} \cos \alpha_M (T - M_f) + \frac{1}{2}$$

$$\xi = C_1 \cos \alpha_A (T - A_s) + C_2$$

$$T = A_f \Rightarrow 0 = -C_1 + C_2$$

$$1 = C_1 + C_2 \Rightarrow C_1 = C_2 = \frac{1}{2}$$

$$\xi = \frac{1}{2} \cos \alpha_A (T - A_s) + \frac{1}{2}$$

$$\alpha_A = \frac{\pi}{A_f - A_s}$$

(Refer slide time: 15:20)

A to M Transformation
 Consider $\xi = C_1 \cos \alpha_M (T - M_f) + C_2$
 $T = M_s \rightarrow 0 = C_1 \cos \alpha_M (M_s - M_f) + C_2$ $\alpha_M = \frac{\pi}{M_s - M_f}$
 $\Rightarrow 0 = -C_1 + C_2$
 $T = M_f \rightarrow 1 = C_1 + C_2$
 $C_1 = C_2 = \frac{1}{2}$
 $\xi = \frac{1}{2} \cos \alpha_M (T - M_f) + \frac{1}{2}$

M to A Transformation
 Consider $\xi = C_1 \cos \alpha_A (T - A_s) + C_2$
 $1 = C_1 + C_2$ when $T = A_s$
 $C_1 = C_2 = \frac{1}{2}$
 $\xi = \frac{1}{2} \cos \alpha_A (T - A_s) + \frac{1}{2}$

$\alpha_A = \frac{\pi}{A_f - A_s}$
 $T = A_f \rightarrow 0 = -C_1 + C_2$

So, it is $C_1 \cos \alpha_M (T - M_f) + C_2$ and this is for austenite to A to M transformation, austenite to martensite transformation. So, this is how we model the graph now all we need to know is the value of C_1 and the value of C_2 . So, if we draw it once again quickly so, we have M_f here we have M_s here we have A_s here we have A_f here and this is the these are the parts. Now we are interested in modeling this graph this part of the graph and we are modeling it by cosine function. So, when the temperature is M_s which means and we are considering austenite to martensite temperature that means, it is following this path.

So, when the temperature is M_s the fraction of martensite is 0. So, T is equal to M_s that tells me that ξ is equal to 0 and then if we put the values $C_1 \cos \alpha_M (M_s - M_f) + C_2$ and also, we have one quantity α_M here α_M is π by $M_s - M_f$. So, α_M is π by $M_s - M_f$. So, this quantity is just cosine of π . So, this becomes zero is equal to $-C_1 + C_2$ because cosine of π is minus 1 and then if you put the other condition which is T is equal to M_f and at T is equal to M_f with the material transform to martensite which means ξ becomes 1 here.

So, ξ is 1 here. So, we have 1 is equal to C_1 and then we put T is equal to M_f when you put T is equal to M_f this quantity becomes 0. So, it is cosine 0 which is 1. So, it is $C_1 + C_2$. Now, we can solve these two equations and find out C_1 and C_2 .

So, C_1 becomes equal to half and C_2 is also equal to half. So, finally, after putting the values the graph the variation is just this half into cosine α_M multiplied by $T - M_f$ plus half where α_M is this. So, that is how we model this part of the graph again we can model this part of the graph also. So, for M_2 martensite to austenite transformation

we can again consider x_i to be equal to C_1 multiplied by cosine α a T minus austenite start temperature plus C_2 and then we can put the boundary conditions. So, when the temperature is increasing when it is at austenite start temperature is A_s .

So, T is equal to a_s at that time x_i is equal to 1. So, 1 equal to and T is equal to A_s means this quantity this cosine quantity is 1. So, it is C_1 plus C_2 when T is equal to A_s and when T is equal to A_f x_i becomes equal to 0. So, T is equal to A_f that tells me that. So, this is A_f and we need to define α_A that is π by A_f minus A_s .

So, when T is equal to a_f this quantity is just π and cosine of π means minus 1. So, at that time f equal to 0. So, that is 0 is equal to minus C_1 plus C_2 and again solving these two we get C_1 is equal to C_2 is equal to half and finally, after putting everything the equation comes to be half cosine $\alpha_A T$ minus a_s plus half. So, that is how this part of the graph this part of the curve can be model and this part of this part of the curve between m_s and m_f or m_s and a_f or between a_s and a_f they are just a constant their values are 0 or 1. Now sometimes it may happen that the transformation starts from a altogether different state.

For example, instead of from here or from here the transformation might come from start from here. So, it may happen that there is a temperature T_0 and at that temperature the material has martensite fraction as x_{i0} as the martensite fraction where x_{i0} is some non 0 value between 0 and 1. So, if the process starts at T is equal to T_0 and x_i is equal to x_{i0} and assume that is somewhere here. So, this point is we can assume to be T_0 and x_{i0} . Now from here if we reduce the temperature, it keeps reducing the, but the x_i remains constant till a temperature of M_s is reached.

So, here we have M_s and here we have M_f . So, till a temperature of M_s x_{i0} is maintained and after that it follows a curve and it becomes x_i becomes 1 when M reaches when It reaches M_f . Similarly, in this part in this part in this side if we increase the temperature, it maintains the same x_i which is x_{i0} till the temperature is A_s and then if the temperature is further increased it does a transformation and x_i becomes 0 when the temperature is A_f . Now this part so, we can show it by a different color. So, this is the initial phase where we have temperature as T_0 and martensite fraction x_{i0} and from here it is starting.

So, from here to M_s it is just a constant and from here to A_s it is just a constant, but from A_s to M_f we need to model it and from M_s to M_f we need to model it and from A_s to A_f we need to model it. Now in the previous case the transformation started from here the so, the initial condition was x_i is equal to 0 at T is equal to M_s , but here the transformation is starting from here. So, the initial condition is x_i is equal to x_{i0} at T is equal to M_s . So, again if the transformation is starting at T is equal to T_0 and x_i is equal to x_{i0} . In this case again we have the same assumption x_i is equal to half multiplied by cosine $\alpha_M T$

minus M_f plus not half I mean half was in the previous set of conditions here we have to keep it free.

So, it is C_1 and plus C_2 . Now we put the initial conditions. So, at T is equal to M_s which is this point we have x_i is equal to $x_{i0} C_1 \cos(\alpha M)$ and T is now M_s minus M_f plus C_2 and we know that this quantity is π because αM is π by M_s minus M_f . So, this gives me x_{i0} is equal to $\frac{1 - C_2}{C_1}$ and then at the end when the temperature is a M_f we have at T is equal to M_f we have x_i is equal to 1 and T is equal to M_f means this quantity is 0. So, it is $\cos(0)$ means 1.

So, it is C_1 plus C_2 . So, now solving these two quantities we get C_2 is equal to $1 + x_{i0} \frac{C_1}{2}$ and C_1 is equal to $1 - x_{i0} \frac{C_1}{2}$. So, finally, the equation looks like $1 - x_{i0} \frac{C_1}{2} \cos(\alpha M T - M_f) + 1 + x_{i0} \frac{C_1}{2}$. See the process starts here and if the temperature is reduced till T is equal to m_s x_i remains constant x_{i0} if it is further reduced then x_i follows this equation. So, this is the path here. Now we will model the other part of it.

So, let us assume that we are increasing the temperature. So, while increasing till T is equal to A_s x_i remains x_{i0} and after that it keeps reducing. So, we have M to A M to a transformation and starting at starting at T is equal to T_0 and x_i is equal to x_{i0} . So, again we have the same consideration x_i is equal to C_1 multiplied by $\cos(\alpha A)$ multiplied by T minus A_s plus C_2 and now we will put the boundary conditions. So, that we have here we can see that when T is equal to A_s when the temperature is austenite start temperature this quantity is 0.

(Refer slide time: 23:55)

If the process starts at $T = T_0$
 $\xi = \xi_0$


A to M Transformation starting at $T = T_0$
 $\xi = \xi_0$

$$\xi = C_1 \cos \alpha_M (T - M_f) + C_2$$


at $T = M_s$ $\xi_0 = C_1 \cos \alpha_M (M_s - M_f) + C_2$
 $\Rightarrow \xi_0 = -C_1 + C_2$
 $C_2 = \frac{1 + \xi_0}{2}$ $C_1 = \frac{1 - \xi_0}{2}$

$$\xi = \frac{1 - \xi_0}{2} \cos \alpha_M (T - M_f) + \frac{1 + \xi_0}{2}$$

M to A Transformation starting at $T = T_0$, $\xi = \xi_0$

$$\xi = C_1 \cos \alpha_A (T - A_s) + C_2$$


at $T = M_f$
 $1 = C_1 + C_2$



Smart Structure

$$T = T_0, \xi = \xi_0$$

$$\xi = C_1 \cos \alpha_M (T - M_f) + C_2$$

$$T = M_s \Rightarrow \xi_0 = C_1 \cos \alpha_M (M_s - M_f) + C_2 \Rightarrow \xi_0 = -C_1 + C_2$$

$$C_1 + C_2 = 1$$

$$C_2 = \frac{1 + \xi_0}{2}$$

$$C_1 = \frac{1 - \xi_0}{2}$$

$$\xi = \frac{1 - \xi_0}{2} \cos \alpha_M (T - M_f) + \frac{1 + \xi_0}{2}$$

$$T = T_0, \xi = \xi_0$$

$$\xi = C_1 \cos \alpha_A (T - A_s) + C_2$$

So, it is 1. So, C 1 plus C 2 and at that temperature xi is equal to xi 0. So, we can write xi 0 is equal to C 1 plus C 2 and then when the temperature reaches A f at that time xi becomes 0. So, here we have 0 and A f means this quantity is pi. So, it is minus C 1. So, minus C 1 plus C 2 is equal to 0.

So, we have 0 is equal to minus C 1 plus C 2. Now, if we solve these two equations, we get C 1 is equal to C 2 is equal to xi 0 by 2 and then if we put it back our xi becomes xi 0 by 2 multiplied by cosine alpha A T minus a s plus xi 0 by 2. So, again when the temperature reduce as increases from T is equal to A s to A f and if the if at T is equal to A s our xi is xi 0 then xi follows this path. Now, so far, we have seen that these transformations are fully temperature driven. If we reduce the temperature the material converts to martensite, if we increase the temperature the material converts to, I mean transforms to austenite.

(Refer slide time: 25:54)

$$\xi_0 = C_1 + C_2, 0 = -C_1 + C_2$$

$$C_1 = C_2 = \frac{\xi_0}{2}$$


$$\xi = \frac{\xi_0}{2} \cos \alpha_A (T - A_s) + \frac{\xi_0}{2}$$

Now this kind of transformations can happen due to stress also. So, a transformation can be purely stress driven or it can be a combination of that. So, these characteristic temperatures M s A s M s A s M f A f they can be dependent on those stresses. So, this is when there is no stress under no stress these temperatures are this M s A s and M f A f. Now, under stress these characteristic temperatures can change.

So, if we look at this the if we look at a graph of how this characteristic temperature changes with stress it looks something like this. So, suppose that our stress is 0 and at 0 stress we have a martensite finish temperature and little higher than that we have martensite start

temperature and then we have martensite austenite start temperature and we have austenite finish temperature. Now, if the material is under stress, then under the stress this temperature shifts towards right. So, at a higher stress the martensite start temperature will be somewhere here the martensite the martensite finish temperature will be somewhere here the martensite start temperature will be somewhere here accordingly the austenite start temperature and the austenite finish temperature. And if we join it if we do it for several values of stresses, we see that we get a straight line.

(Refer slide time: 29:43)



So, these are all are straight lines. So, this is we can say M_s M_f M_s A_s A_f and as we keep increasing the stresses these characteristic temperatures keep increasing and this variation of characteristic temperatures which are our M_s M_f M_s A_s A_f I am writing in the ascending order of the temperature of the value and this temperature the variation of this characteristic temperatures with stress is generally linear and this is experimentally observed. And also, if we look at these straight lines generally in most of the cases the slope of the straight lines corresponding to M_s M_f A_s and A_f are more or less same and these are basic experimental observation for most of the materials. Now the question is if the material is simultaneously is under some nonzero stress and then the temperature is varied then how does this transformation equation look like. So, that we will see in the next class let us stop this lecture here. In the next class we will bring in the effect of stresses in those transformation equations and we will see beyond that.

So, with that let me conclude the lecture here.

Thank you.