


Advanced Electric Drives
Prof. S. P. Das
Department of Electrical Engineering
Indian Institute of Technology, Kanpur

Lecture - 20

Hello and welcome to this lecture on advanced electric drives. In the last lecture, we are discussing about a cyclo converter fed synchronous motor drive with unity power factor action, as you know the synchronous machine as a field winding; in case of round synchronous machine we have a field winding. And synchronous motor can operate in leading the power factor, in unity power factor or magnet power factor. As a special case sometime it is beneficial to operate the machine under unity power factor condition. That is what we discussing in the last lecture.

The advantage of operating and induction the synchronous motor under unity perfect operation is that, it only takes active power; the power is only active there is no reacting power, hence the efficiency of the overall system is maximized. So, if we see the block diagram that way discussing in the last lecture.

(Refer Slide Time: 01:19)




In the block diagram we have the cyclo converter this is the cyclo converter that we have. And cyclo converter is fielding the armature for the synchronous machine this is the armature of the synchronous machine. And the field winding is fed from different

converter that is 6 power converters which is fielding to the field winding. And the cyclo converter if you see this has got 2 anti parallel phases of converter in each phase; phase a has got a positive s c r bridge and also a negative s c r bridge similarly, phase b have got positive s c r bridge and negative s c r bridge and phase c also have positive s c r and negative s c r bridge.

Now, in each phase the current is alternative and hence we need 2 converters one for the positive current and one for the negative current; in fact, we need 2 bridges. So, per phase we have 2 bridges one for priding the positive current, other for priding the negative current. And the field winding is separate 6 power converter that is we are talking about in this case. And the whole system is operated in such a way that the power factor is unity.

(Refer Slide Time: 02:47)



And, how the power factor is unity that we can see by referring to the phasor diagram that we have already seen in the last lecture. So, in this case you know that this is the magnetization current i_m . And the magnetization current and the armature voltage V_a are perpendicular each other this angle is 90 degree. So, see this angle is 90 and V_a which is also have been 90 degree with i_m is in parallel with V_a this is i_a and this is also i_a . So, in fact what we have; we have 2 lines which are parallel i_a here and i_a here; because this angle are 90 we have 90 degree here, also 90 degree here. So, as a result we can see

that the current i_a is in phase with the armature V_a . So, which means the power factor is 1 power factor is unity or θ ; power factor angle is equal to 0.


So, to impress this particular condition; we have to control the field current as per this equation the field current i_f if you see this right angle triangle; this right angle triangle one side is i_m' the other side is i_a the armature current and the third side is i_a , i_f is along the field axis. So, we have the field poles here this is the field pole. So, i_f is along with the field axis or the d . So, this triangle 1 side is i_f other side is i_a and the third side is i_m' and i_m' is magnetization current. Now, to ensure that this right angle triangle exist we can find out i_f by the relationship. So, i_f is given as i_m' by $\cos \delta$.

Now, what is this δ ; this δ is the torque angle. δ is this angle which is the angle between the d axis and the stator flux; the stator flux is along the magnetation current the stator flux is ψ_s . And the stator flux linkage is along the magnetation current direction triangle between the phase and the d axis is the torque angle. Now, if you find out the reference field current it means when the synchronous machine is operating we have to adjust the field current. The field current has to be adjusted in such a way the power factor is maintained at unity.

So, in other words the field current i_f is control as i_m' by $\cos \delta$. So, this δ has to be find out and to find out δ what we need; we need the torque angle is estimator. So, this is the torque angle estimator which is a block in this particular block diagram they it is a computational block. And out of this we get the torque angle that is δ and the torque angle is fed to this calculation block and we get the reference field current as i_m' by $\cos \delta$. So, what is this torque angle estimator? So, the torque angle estimator take input as the i_a ; the armature current i_b the armature current is phase b . Since, we have let assume a torque connected machine if you know i_a and i_b we can find out i_c ? i_c is equal minus of i_a plus i_b .

So, in fact we can calculate the third current by just having the knowledge of i_a and i_b . And the field current all current can measure by using hall sensors. So, we have the hall sensor to measure i_a , i_b and i_f . So, with this information we need to find out what is the torque angle?

(Refer Slide Time: 07:06)



Now, we have seen that the torque angle is angle between the stator flux linkage and the d axis. Now, this is the d axis; d axis is the same as a pole axis we having the field in the rotor the field is moving away the d axis; of course not stationary it is also moving away it is moving at a speed of the rotor. So, this is the rotor speed. So, d axis is moving away with the speed of the rotor. So, what we do we find out the component of this flux linkage along the d axis. So, we can find out the component of this along the d axis. So, we can project this along the d axis. So, this component is called psi d s; the stator flux linkage in the d axis.

Similarly, we have a q axis and the q axis is orthogonal to d axis; this is the q axis which is having right angle or phi by 2 with the d axis. And again we can project the stator flux linkage along the q axis. So, if you project the stator flux linkage along with the q axis this flux is called psi q s for the flux linkage in the q axis. So, if we know the individual component psi d s and psi q s; psi d s is the flux linkage in the d axis, psi q s is the flux linkage in the q axis we can find out what is delta; delta is this angle right. So, if this is psi q s this is also psi q s, this angle is also 90 degree all right.

So, we can calculate delta provided we know psi d s and psi q s. So, delta is calculated by what is called a torque angle estimator block. And we can say that delta is equal to tan inverse of psi q s by psi d s. So, to find out delta is the information about the q axis stator flux that is psi q s and also about the d axis stator flux that is psi d s. So, how to find out

this ψ_d and ψ_q and how to find out this; let us remember the equivalent circuit of the synchronous machine in the respective axis. So, we have already seen the equivalent circuit in d and q axis.

So, let us try to derive this equation or this ψ_d and ψ_q from the equivalent circuit. So, if you take d axis equivalent circuit. So, what will have here we have been a back emf and resistance drop leakage induction then we have magnetizing induction here in the d axis. And then we have the leakage induction of the damper winding the resistance of the damper winding.

And then we also have the field winding leakage and the field winding resistance and the field winding voltage. So, this is our with v_d have the voltage and this is the resistance the stator leakage induction that L_s in the d axis. And this is magnetizing induction L_m in the d axis and this part is the damper the damper leakage induction in L_k , damper resistance this r_k , the field leakage is L_f , L_{lf} . And the field resistance is r_f and the field applied voltage is v_f all right.

So, these are the variables that we have here the parameters. And we have the current in case this is the d axis stator current i_d ; this is the damper current in the d axis entering this junction that is i_k . And this one is the field winding current that is i_f . So, we have to find out what is the magnetization current and the magnetization current in this case in the d axis is i_m . So, we are talking about solid for machine. So, we are drawn d axis in flux circuit. Now, we have to find out stator flux linkage; the stator flux linkage is the flux linkage associate with the magnetizing branch and the stator linkage. So, this is ψ_d ψ_d is the flux linkage associate with the magnetizing branch and also the stator linkage stator linkage inductions.

Now, to find out this ψ_d we have to find out what is i_m ; i_m is produced by 3 currents i_m is magnetizing current in the d axis; which is produce by the stator d axis current, the damper is current and also the d axis field current. So, in fact we can say that this i_m is basically produce by this currents. And of course we do not know the damper current; the damper current is the current which we cannot measure; we can measure the field current because field is the available the terminal are available. So, we can sensor to measure the field current, we can also measure the stator current we can also sensor in the stator to measure the stator current.

But unfortunately we cannot measure the damper currents; damper currents is hidden inside the machine, damper is part of the field the rotor and the damper current are not available for measurement. So, we have to somehow get the magnetizing current in terms of the field current and in the stator current. So, what is $i_m d$. So, if you find out what is $i_m d$ we can take this circuit we can take only this part of the circuit this is $L_m d$. So, we have a current which is entering here is $i_d s$; the current which is entering from this side from the field is $i_f d$. And the current which is with coming from the damper of course the damper current is not known. So, if we just replace by the damper parameters this is $r_k d$ and this is $L_k d$ and this current is $i_m d$.


So, we need to find out what is $i_m d$ in terms of $i_d s$ and i_f . So, we can apply this basically current divided circuit. So, we have the current which we have the 2 currents here and the currents are $i_d s$ and $i_f d$; the stator current and the field current they are basically divided partly in the partition branch and partly in the damper branch. So, we can find out $i_m d$ in the following way $r_k d$ plus $L_l k d p$ divided by $r_k d$ plus $L_l k d$ plus $L_l d$ into p ; this is small p is the derivative operator this is d by $d t$. So, this dynamic equation will give us $i_m d$ by simple current division principle.

So, if we know what is $i_m d$; we can find out the stator flux linkage in the d axis. So, what is $\psi_d s$? $\psi_d s$ is taken as $L_l s$ into $i_d s$ plus $L_m d$ into $i_m d$. So, if you want find out the flux linkage we have to 2 terms here; the leakage flux that is $L_l s$ into $i_d s$ and then plus $L_m d$ into $i_m d$. So, this we can simplify and expand this that is $L_l s$ into $i_d s$ plus $r_k d$ plus $L_l k d p$ divided by $r_k d$ plus $L_l k d$ plus $L_m d p$. And then we have got $L_m d$ here again we have multiply with $L_m d$. And then the currents will be can be written here we can write the current and the currents are $i_d s$ plus $i_f d$. So, this is the expression for $\psi_d s$.

Now, we can see here to find out $\psi_d s$ we have to know $i_d s$; $i_d s$ this can be measured by having hall sensor we can measure i_a , i_b , i_c ; if you know i_a , i_b , i_c you can transform that into d and q component in the rotor. So, we can have $i_d s$ and $i_q s$. So, in fact $i_d s$ and $i_q s$ are measurable. So, we have got information about $i_d s$; the field current $i_f d$ can be measured having sensor in the field circuit. So, we know $i_d s$ and i_f and the parameters have a machine are given; we know the stator parameters, stator inductions, we know the machine age inductions, we know the damper parameters. So, we

can find out ψ_d by the equation. And these equations all quantities are known, the parameters are known, the currents are also known.

(Refer Slide Time: 19:48)



Now, similarly, we can calculate the stator flux in the q axis. So, I will just draw the q axis equivalent circuit. Now, this equivalent circuit is actually in the rotor reference frame given this one also is in the rotor reference frame. So, here exactly in the same way we have the back c m f in the q axis, the stator resistance in the q axis, the stator linkage inductions, then we have the mighty age induction and then we have the dumper parameter. In the q axis we do not have any field winding; the field winding present in the d axis. So, in the q axis in the rotor we only have the dumper winding.

So, we can have the dumper linkage inductions and will have dumper resistance. So, this is r_{kq} and this is L_{kq} dumper linkage inductions and dumper resistance refers to the parameter, refer to the stator. Then here the mighty age induction is L_{mq} in the q axis the stator linkage induction is in fact same because of the stator is a symmetrical stator having 3 windings which are symmetrical. So, we have same linkage induction in the stator that is L_{ls} ; stator resistance will also be the same that this is r_s and this is applied voltage in the stator v_{q_s} . Now, similarly the current entering here is i_{q_s} and this current is the magnetation current which is going in the magnetation branch that is and i_{m_q} .

So, if you want find out what is the q axis stator flux linkage; we can do that by this equation ψ_{qs} is equal to L_{ls} into i_{qs} the linkage flux plus the magnetation flux which is L_{mq} into i_{mq} . Now, again in the similar passion the stator flux linkage in the q axis in the flux linkage associated with the magnetation branch and the stator linkage. So, this is ψ_{qs} . So, this is basically given by this equation ψ_{qs} is the is equal to L_{ls} into i_{qs} ; that is the linkage flux in the q axis plus L_{mq} into i_{mq} that the magnetation flux in the q axis. The formation of the 2 gives us the q axis stator flux linkage.

Now, how to find out i_{mq} similarly we can do that as we have done previously will draw only this part of circuit this is L_{mq} . And this part is the dumper part in the current which is entering this particular branch is i_{qs} . And this current get divided into 2 parts; one is in the magnetation branch other is in dumper circuit. So, we are only interested in i_{mq} . Now, this is current divided circuit we have 2 parallel branches and other current will be divided into invert proportional to there in inducters. So, we can calculate what is i_{mq} i_{mq} in this case can be given us this is L_{lkq} the linkage inductions the resistance r_{kq} .

So, we have r_{kq} plus L_{lkq} ; p is derivative operator divided by the total interiors of the circuit r_{kq} plus L_{lkq} plus L_{mq} into p into i_{qs} . So, this basically gives magnetation current in the q axis. So, once we get the magnetation current; we will be in a position to find out the total flux linkage in the q axis that is ψ_{qs} . So, ψ_{qs} in this case ψ_{qs} is given us r_{kq} plus L_{lkq} p divided by r_{kq} plus L_{lkq} plus L_{mq} p . And we have to multiply with L_{nq} because we are talking about flux linkage in to i_{qs} plus leakage flux that is L_{ls} in to i_{qs} .


Now, if you see if we analyze this expression for ψ_{qs} ; we see that is the ψ_{qs} expression in the right hand side all the variables are known; the currents i_{qs} can be measured by having all sensor in the armature we can measure the various currents i_a , i_b , i_c . And once we measure the 3 phase current; we can transform the 3 phase current in to the rotor reference frame in to i_{ds} and i_{qs} respectively. So, in fact i_{qs} is measurable and the parameters of the machine like the damper parameter in the q axis the leakage inductions these are available to us. So, in the right hand side of this equation all the values are known. So, we can find out what is i_{qs} . So, we have already seen the calculation of ψ_{ds} .

Now, we have in able to derive the expression for ψ_{qs} to; so this basically to a dynamic equation. So, giving the currents and the parameters we can find out the flux linkage. And from the flux linkage as we have already seen that we can calculate the value of delta; delta is the torque angle and that is equal to $\tan^{-1}(\psi_{qs} / \psi_{ds})$. So, this is how we implement the block torque angle estimator all this calculation are done in real time; of course if you see this expression for ψ_{ds} and ψ_{qs} we will see that ultimately we have to implement a few integrators p is the derivative terms; so we have p in the numerator and also t in the denominator.

So, ultimately this will lead to something like an integrating action finally. And then we have the summation in this case. So, that is no derivative term in the final implementation of ψ_{ds} ψ_{qs} . So, once we find out ψ_{ds} and ψ_{qs} ; we can calculate the torque angle delta which can for control of synchronous motor. Now, we have also seen that in the synchronous motor control we also need θ_r ; θ_r is the rotor position rotor is moving away; the d axis is moving away the rotor is continuously rotating member.

And, then also we need the expression for the speed. And this θ_r and the speed are obtain using an angle resolver; angle resolver stand for A R; A R is the angle resolver. So, the angle resolvers give us information about θ_r and ω_r . Now, what is an angle resolver? Traditionally angle resolver actually gives us the cos and sign angle of the rotor. But now a days we have availability of incremental encoders and also absolute encoders to implement this angle resolver.

(Refer Slide Time: 28:50)



So, we have 2 types of encoders; the encoders are we are actually discussing about the angle resolver that is A R. So, this can be the objective is to find out theta r and omega r. And this can be obtained by using incremental encoder; the incremental encoder gives us pulses as a rotor rotates. So, it gives us tame up pulses like high and low signal like this. So, this is the output of an incremental encoder; in fact this incremental encoder actually gives us 2 signals which are in quadrature. So, this is one channel of the other channel of the encoder will basically gives us again a tame up of which is basically shifted from the other pulse by phi by 2.

So, this is maybe we can call this should be X pulse this will be Y pulses. So, this 2 are the output of the implemental in encoder; in addition to that encoder is also gives another signal marker pulses; marker pulses give once revolution. So, this pulse just gives one pulse in a revolution like this. So, this is may be the signal call Z. So, if we use implemental encoder which is not very expensive; which can be very easily mounted on the rotor will have 3 signals X, Y and Z and in this case X,Y are in quadrature. So, depending upon the rotation of the rotor the direction of the rotation X may lead Y for Y may lead X.

So, by counting this number of pulses; we can get information about theta r. So, theta r can be obtained by properly counting the number of pulses counting out of the encoder let us say X. So, if we take 1signal let say X; if we count number of pulses will be able to

have information about θ_r . Now, what about the direction; the direction can be obtained by seeing which pulse is leading which one. So, the direction information can be obtained by ((Refer Time: 31:56)) which can be used to find out with X is leading Y or Y is leading X. The direction of rotation can be obtained by finding out the phase angle or the lead lag information between X and Y.

And, what is the role of marker pulse; the marker pulse actually when we are continuously incrementing and trying to find out θ_r ; angle actually cannot be higher than 360 degrees; when you are talking about 1 revolution this is 360 degree mechanical. So, 720 is same as 360. So, in fact this marker pulse actually synchronous the signal. So that the cumulative error is reduced. So, marker pulse gives the indication of a start of the counting and this is also used to synchronize; so that the cumulative error in the counting is made 0. So, the marker pulse Z is used to make the cumulative error in counting 0. So, this is about incremental encoder which is not very expensive.

Now, if you want to find out the exact θ_r irrespective of the rotation; we can go for what is called an absolute encoder it is expensive; an absolute encoder are available either in the binary coded form or in the gray coded form; we can have the option to choose whether to go for a binary coded form or gray coded form. So, the absolute encoder will give us a unique combination of the pulses. So that we can find out the value of θ_r . So, the second is to go for absolute encoder they can be get either 4 bit, 8 bit or 12 bit. So, what we are getting in this case we are getting 4 bit at a time or we are getting 8 bit at a time or we are getting 12 bit at a time.


So, when we are getting multiple bits at a time this combination of the bits will give us an information about the rotor position; since, we have large number of wires it is naturally expensive. So, they are actually preferred for those application where the absolute encoders are really necessary. So, in this case the combination of bits gives the information about θ_r .

And once we signed out θ_r we can differentiate this information at what rate θ_r is changing. And $\frac{d\theta_r}{dt}$ will give us ω_r . So, after finding out that we can calculate this ω_r by having this expression that $\frac{\Delta\theta_r}{\Delta t}$ is a rotor speed that is ω_r . So, this is all about angle resolver. So, the angle resolver is an essential part of synchronous machine. Because without this angle information a

synchronous motor cannot be controlled; it can only be control provided we have some angle information.

So, we are discussing about the control of synchronous machine. So, we have seen how we can implement the torque angle estimator and also an angle resolver. And synchronous motors are usually controlled in close loop fashion with a rotor position feedback; we will go to a new topic that is on permanent magnet motors. So, this permanent magnet motors are very widely used for various applications; the reason of behind their popularity is the compactness.

(Refer Slide Time: 37:03)



So, today will be discussing about permanent magnet motors; they are popular because of high torque to weight ratio the field winding is replaced by permanent magnet. And hence we do not have any field excitation; the permanent magnet keeps the flux and the armature is the conventional armature. And there is interaction between the permanent magnet flux and the armature current and hence a torque is produced. Now, if we see the classification of this permanent magnet motors essentially we have 2 types of permanent magnet motors. The first one is the conventional permanent magnet d c motors were the armature is a rotor and the field is a stator the field winding is replaced by a permanent magnet.

So, number 1; types of permanent magnet motors the first type is conventional d c permanent magnet motors. Now, in this case the armature and the commentators


segments and the brushes are just like that of a normal d c motors. But the field windings which are in the stator are replaced by permanent magnets. So, we have the armature here, we are having the brush in this case. But instead of a wound field what we have here; we have a permanent magnet field. So, this is a structure of a permanent magnet d c motor the conventional one. And we have the armature and we have the field winding the field winding are having permanent magnets; these are the permanent magnets in the field winding.

And, when we mount this permanent magnet basically the magnet comes in pairs and this is north, south. And this basically these are the pole shoes. And similarly here we have the pole shoe as a magnet is placed here we have south and north. So, we have 2 magnets. And one gives the North Pole other gives the south pole for the working of the d c motor. Now, these type of motors are also very popular for low power video per application; we also have another type of permanent magnet called brushless d c motor and also permanent magnet synchronous motor.

Second type of permanent magnet motors are brushless d c motors and permanent magnet synchronous motors and that is called P M S Ms. So, this 2 types of motor like brushless d c motor and permanent magnet synchronous motor; the construction is somewhat similar to that of a conventional synchronous machine. In the synchronous machine the field winding is on the rotor, the armature is on the stator as we already seen.

But the field winding is replaced by a permanent magnet field there is no winding in the rotor, there is no field winding in the rotor; instead of conventional field winding we have the magnets the permanent magnets in the field winding. Now, before we talk about the details of this permanent magnet motors; let us have some basic idea about the working of this permanent magnet motors, and something about the material the permanent magnet material.

(Refer Slide Time: 41:57)



So, we will see the principle of permanent magnet motors; in fact we have to we can discuss about principle of permanent material. Let us take a permanent magnet material, let us take ring separate permanent magnet material and let us caught an air gap. So, we will take a ring in this case and then what will do here will caught a air gap. So, this is a permanent magnet may be an idiom material and then this is having an air gap which is of length L_g and this is having a circular cross section. And the cross section this is iron part and this is the air gap and the length of the iron part is l_i . So, this is the length of the iron part from this side we have a l_i . And the cross section area here is A_i similarly the length of the air gap is L_g and the area of this air gap is A_g .

So, usually when we talk about a magnetic material they follow what is called the B H characteristic. So, if see the B H characteristic of a typical material this is the H; H is the field strength which is usually the unit is ampere term per meter. And the first density is B and the unit is usually tesla or Weber per meter square; tesla is same as Weber per meter square. So, if we plot the B H characteristic we have various types of material; we can have a soft material, we can also have a hard material. So, if we plot the B H characteristic it starts like this as we increase the H or the field strength the flux density increases; then after some time it is saturates with the increase of the field strength age the flux density no more increases. And then if we decrease the field strength the flux density decreases but in a different path.

And, then if we make age negative flux density for the decreases and sometimes this becomes equals to 0. Then we further increase H in the negative direction if reverses. So, B becomes negative and then we increase H after that. So, H will reduce to increase to 0 and then H will become positive. So, this is how they path is stretched and this is what we call a B H characteristic; sometimes if we see there some of the material have got very small B H look. And in this case if you see that the reverses path and the forward path they do not coincide. And the lope inside this 2 paths enclosed is called the B H lope; in a soft magnate this B H lope is quite small in hard magnate material the B H lope is quite large.

So, in this B H lope we have got some important property this is called B r; B r is basically the flux density for H equal to 0; this is called residual magnetism or remanent magnetism. So, B r is called residual magnetism or remanent magnetism all right. And when we make H negative B becomes equals to 0 and the value of H for which B becomes equals to 0 is cold H C; H C stands for the coercive force. So, we have B r is the residual flux or the residual magnetism and H C is the coercive force. So, these are the important 2 important quantity is of magnate material. So, in this particular lope we have lope structure circular permanent magnet; in which we have caught air gap of length L g.

Now, in this case you know that we do not have been in a current. So, since we do not have been in a current; we can say that the total ampere turn is equal to 0; if you take this magnetic part we have partly iron and partly air gap there is no exciting current; even if we have the quail here the quail can we thought of we can half of quail like this and the quail is not carrying in the current.

Now, in the absence of an external current we can say the total ampere turn drop in this lope is equal to 0. So, we can say that total ampere turn is equal to 0. Now, that will give as this equation that the ampere turn in the iron is $H_i l_i$; H_i is the field strength in the iron and l_i is the length of iron plus $H_g l_g$; H_g is the field strength in the air gap and l_g is the length of the air gap that is equal to 0 or we can say that H_i is equal to $H_g l_g$ by l_i with a minus sign.

So, we can say that H_i is equal to minus $H_g l_g$ by l_i with a minus sign it is a negative quantity. So, now again we can say that when your we have a lope the flux will be the

same we have the same common flux. Because the same flux is passing through this loop the flux lines or basically passing and they are crossing this and entering. So, the flux lines are basically closed line. So, whatever flux is in the iron the same flux is the also passing in the A R. So, we can say that we have a common flux here. So, what is flux is flux? Flux is flux density in to the cross external area.

(Refer Slide Time: 50:21)

The whiteboard contains the following equations:

$$\phi = B_i A_i = B_g A_g$$

$$B_g = \frac{B_i A_i}{A_g}$$

$$\mu_0 H_g = \frac{B_i A_i}{A_g}$$

$$H_g = \frac{B_i A_i}{\mu_0 A_g}$$

$$\mu_0 = \frac{B_g}{H_g}$$

So, we can say here that phi is equal to B i in to A i in the flux in the iron is B i in to A i flux density of the iron in to cross external area of iron is equal to B g in to A g; the flux density of air gap into the cross external area of the air gap. So, this is the flux passing in the particular loop. Now, we can say that what is B g? Now, B g is equal to B i, A i by A g all right. So, B g is equal to B i, A i by A g.

Now, we know that mu naught is equal to B g by H g. H g is the field strength, B g is the flux density. And their related by a content of prop personality curve permeability constant. So, this is mu naught is the constant of permeability of free space; since, we have air gap they are it is mu naught. So, mu naught is equal to B g by H g.

So, we will replace this B g in the following fashion that mu naught in to H g is equal to B i, A i by A g or we can say that H g is equal to B i, A i by A g by mu naught. So, this is what we have here. Now, this H g we can take from this equation or replace it is in the previous equation. In the previous equation we have H g term here. Now, this is our H g now this h g we can replace by what we have here is B i, A i by A g by mu naught. So,

we can say that is equal to minus B_i , A_i by μ_0 by A_g in to l_g by l_i it is interesting equation; where we have H_i equal to minus of B_i , A_i by μ_0 A_g in to l_g by l_i .

Now, if you see the right hand side in the right hand side; we have the flux density B_i , A_i a_i is the cross external area l_g l_i . So, these are all positive quantities the area is positive, the lengths are positive, the μ_0 is positive. So, we are seeing that H_i and B_i are opposite side to each other. And hence in a material where we have caught air gap the casuistic operates in a second quadrant.

So, this is basically the second quadrant were B_i and H_i are of opposite side. So, in all permanent magnet motor they operate in the second quadrant were B_i and H_i are of opposite side. So, in the next lecture we will see how we can take a specific a permanent magnet material. And how we can construct the field winding or the field or the stator that will be discussing in the next lecture.