

Course Name: Design of Electric Motors

Professor Name: Dr. Prathap Reddy B

Department Name: Electronic Systems Engineering

Institute Name: Indian Institute of Science Bengaluru

Week: 06

Lecture: 30

Title: Electric Machine Sizing Equations-Output Power Equation in terms of D^3L Product - 1

Greetings to all, in the last lectures we have discussed the design equations in terms of volume product right. In that equation we have not considered the stator geometry like what is the stator outer diameter, what is the rotor outer diameter, rotor inner diameter as well as slot geometry or slot area and then flux densities at the back iron and flux densities in the teeth we have not considered. Only we considered at the air gap what is the flux density, what is the current density and what is the inner diameter of the stator based on those three variables we have defined the power equation right. So, in order to include the flux densities at the different parts of the stator and rotor and slot areas of the stator as well as rotor and stator outer diameter as well as rotor outer diameter and rotor inner diameter all these geometries and along with that actual current densities like if you will see the actual current density is happening inside the slot right more current density. So, with respect to the actual current density we will derive the power equation. So, from that power equation we can find the physical dimensions of a machine like outer diameter as well as inner diameter of the stator and length of a core ok.

Let us consider a three phase machine we can see here three phase machine having a outer diameter of D_{s0} and inner diameter D_{is} and inner diameter of the rotor is nothing, but D_{ir} and D_{r0} are the outer diameter of the rotor and l_g is the air gap diameter sorry air gap length l_g is equals to air gap length. In the previous analysis we have not considered the slot geometry and we have not considered the outer diameter of the rotor right. In this analysis to find the accurate power equation we will consider the flux densities at the back iron that is B_c and flux densities at the teeth that is B_t and flux density at the air gap that is B_g value. So, we will see the all possible magnetic flux densities at different parts of the iron.

Here we can see that the maximum flux density will happen in this region right where the area is less. In this region we will see the maximum flux density right as compared to the

air gap as compared to the core this portion. This portion is the core portion and this portion is the air gap this is the core portion. So, flux densities at the different parts we will consider and along with that thing we will see the actual area of the slot. We will consider the actual slot dimensions like slot area if you want to represent then this is the slot area.

So, by considering this slot area we will derive the power equation in terms of d cube l product this is the slot area A_s . And the slot dimensions we can see here back iron length is d_c and the radius from this portion to this portion from this point to this point the radius is r_2 and this portion is d_s . And similarly this one is r_1 and between this gap this gap is nothing but d_{naught} and air gap length is l_g and the width of the teeth is nothing but t_{small} t and the inner diameter is D_i s and outer diameter is D_{naught} s these are the different dimensions of the stator core. So, by considering all these dimensions we will find the power equation in terms of B values and then electric loading values and then slot dimensions. So, B_g B_t and B_c different flux densities we will consider for deriving the power equation.

So, first we will see the flux densities at the different portions of a stator core. We will see the flux lines how the flux lines are flowing. So, here flux lines are coming in this manner and in the core back iron the flux lines are in this manner. So, our task first task is to identify what is B_c what is B_t and then what is B_g flux at the core and flux in the teeth and flux in the air gap and along with that find the slot area. First step I will start with the flux density at the air gap peak flux density that is B_g peak we have to find in terms of flux.

In the average flux in the core average flux in the teeth average flux in the air gap it will be same. The flux inside the core will be same if we neglect the fringing and everything then flux in the core also is same. Now, in order to find the flux density maximum at the air gap consider the flux average is equals to 2 by π flux peak value. Here flux in terms of B and A we can write it B_g peak into A . Area A is nothing but area of cross section with respect to that particular flux lines.

Here area is nothing but B_g peak value into πD_i s into l_e by p . This part is with respect to the x and this part is with respect to the y . x into y we can get the area with respect to the cross sectional area for air gap flux. Just find the area here with respect to this flux lines perpendicular cross sectional area that is πD by P with respect to the one particular pole and l_e is the length of a core. Then B_g value is equals to B_g peak equals to flux average into P divided by 2 into D_i s into L_e .

This is equation number 1. Next, we will find the flux density at the teeth. So, generally the teeth area will be smaller. We can observe in this figure. So, that the teeth area is nothing but this one.

The teeth area is smaller. So, because of that reason the flux density will be higher in the teeth portions. We will find that value exactly what is flux density at the teeth peak value. So, again flux at the teeth is nothing but average is equals to $2 \text{ by } \pi \phi_t \text{ peak value}$. So, here $2 \text{ by } \pi$ is constant flux is nothing but $B \text{ into } A$, $B_t \text{ peak into area}$ is nothing but cross sectional area with respect to this portion we have to calculate.

So, here cross sectional area with respect to this particular point is nothing but $y \text{ axis is length into some stamping factor } k_s$. Here k_s is the steel stamping factor or steel stacking factor and l_e is the effective length of a core including the air ducts and $y \text{ axis length is what } t \text{ is width of a single teeth like that } n \text{ number of teeth are there in the on the stator circumference}$. We can see here t is the width of one particular teeth, one particular teeth width is t . So, like that how many teeth are there under one pole or how many teeth are there under hover a circumference is nothing but Q_s is nothing but number of stator slots into t . Then teeth length we have identified in a complete stator circumference per pole if you want then by P we have to add this is the total area.

Then $2 \text{ by } \pi B_t \text{ peak } Q_s \text{ into } t \text{ le } k_s \text{ divided by } P$ this is the average flux at the teeth. So, maximum flux density at the teeth is nothing but $\pi \text{ by } 2 \text{ into flux average into } p \text{ divided by } Q_s t \text{ into } le k_s$. So, the flux average I am considering same. So, $\phi_t \text{ average}$ or $\phi_c \text{ average}$ or $\phi_g \text{ average}$ all things I am representing as a $\phi \text{ average}$. So, this is equation 2.

Next what is the flux density at the core or back iron? So, look at here the lamination of the stator core this is the back iron this one above the slots this portion from here to here is the back iron. So, how to find the flux density at that particular point? We will see the area where the flux lines are coming this is the place where the flux maximum flux lines are entering into the teeth. So, we have to find the area with respect to that particular point. Now, the flux core average value is nothing but $2 \text{ by } \pi \text{ flux at the core peak value}$ that is $2 \text{ by } \pi B_c \text{ peak into } A$ here A is the area of cross section in order to find the area of cross section $y \text{ axis length is nothing but } le \text{ into } k_s$ le is the effective length of the core and k_s is the steel stacking factor and $x \text{ axis direction we are finding with respect to this manner perpendicular cross sectional area } x \text{ axis length will be } \pi \text{ into } D_{\text{naught}} s \text{ minus } \pi \text{ into } D_{\text{naught}} s \text{ minus } 2 d_c$ this value is d_c the back iron width by 2 mean we have to take then this will results in $d_c \text{ value } \pi \text{ into } d_c \text{ into } le \text{ into } k_s$ is the area. Then the final equation with respect to the $\phi_c \text{ average}$ is nothing but $2 \text{ by } \pi \text{ into } \pi d_c \text{ back iron width length of a stator core and steel stacking factor into } B_c \text{ peak}$ that results in $B_c \text{ peak equals to } \phi \text{ average divided by } 2 \text{ into } d_c \text{ into } le \text{ into } k_s$ this is equation 3.

Now, we have calculated the flux densities at the different parts B_g at the air gap B_t at the teeth B_c at the core since the area with respect to the teeth is higher. So, B_t value is greater than the B_g and next B_c and B_c is greater than B_g value with respect to the flux is same and area is different for different portions. So, based on that relation we can

conclude that the maximum flux density will happen at the teeth the maximum next flux density at the core and the next case will be at the air gap. Now, we will see the ratios like B_t max flux densities at the different portion what is the ratio B_g by B_t is nothing but equation 1 divided by equation 2 it will results in B into ϕ average divided by $2 D_i$ into l_e divided by π by 2 flux average into P divided by Q_s into t into l_e into k_s . Then this ratio will be Q_s into $t k_s$ divided by π into D_i just rearrange the terms finally, the teeth width we have to solve.

So, the teeth width is equals to B_g by B_t constant value into π into D_i divided by Q_s into k_s this is equation number 4 we have find the teeth width. Similarly, find the back iron length or back iron width d_c by taking the ratio of B_g by B_c that is equals to equation 1 divided by equation 3. So, finally, after solving this expression we will see d_c is equals to back iron length B_g by B_c constant into inner diameter of the stator divided by number of poles into steel stacking factor this is equation number 5.

Now, consider the slot dimensions we will take the we will go back the same image here analyze the slot area as well as different diameters. See here we have to analyze the dimensions with respect to the rotor as well as stator and slot dimensions.

So, the slot dimensions we can see here with respect to the different parameters how the slot dimensions are there and with respect to the stator outer diameter as well as inner diameter we can write the equations in terms of D_i and D_{naught} and slot dimensions. So, that is outer diameter of the stator is equals to inner diameter of the stator plus 2 into D_{naught} is the slot opening height plus r_1 plus d_s plus r_2 plus d_c and D_{naught} outer diameter of the rotor is nothing, but D_i minus $2 l_g$ this is equation number 6.

These equations I have derived from the figure the from the slot image figure we can see here. So, this value is d_c r_2 and then d_s and then r_1 from here to here and slot opening is d_{naught} and remaining one is the l_g value. Now, perimeter of the slot with respect to the w_1 .

So, if I want to calculate the perimeter in this line where w_1 and t we know width of the teeth as well as width of a slot at the bottom side we know. That means, the perimeter of the stator in terms of w_1 Q_s into t plus w_1 is equals to d_i plus 2 into d_{naught} plus r_1 into π right. So, here Q_s is the number of slots into t plus w_1 is nothing, but this width. So, like this how many widths are there Q_s . So, Q_s into t plus w_1 is nothing, but the perimeter actual perimeter we know that d_i plus $2 d_{naught}$ plus r_1 this length we know up to this point length we know right up to this point that is d_i the remaining one is nothing, but 2 into d_{naught} plus r_1 add that thing into π is nothing, but circumference this is equation 7.

Similarly, the perimeter with respect to the w_2 at the slot top side at this particular point where w_2 we know and t also we know q_s into t plus w_2 is equals to d_{naught} s in

terms of D_{naught} we can write it right $D_{naught} - 2$ into d_c right back iron length d_c plus radius at the bottom side of the slot into π is equation number 8 or we can write in terms of D_I also D_I means plus the remaining terms $d_{naught} + r_1$ this is d_{naught} and $d_s - r_1 - r_1$ up to r_1 we have to write d_s into π this 2 comes under same equation number 8 a and 8 b.

We have find the perimeter or circumference with respect to the w_1 and w_2 this equations involves in inner diameter of the stator as well as outer diameter of the stator D_{naught} and slot geometry slot geometry we can see the slot opening and the radius at the bottom side of the slot that is this one this radius is nothing but r_1 and this radius here is nothing but r_2 we can see here this radius is nothing but r_2 this radius and this radius is nothing but r_1 next task is to find the area of the slot. Now, we have calculated the flux densities at the different parts and the slot information now area of the slot we will find. So, the slot we have considered in this manner this is the slot dimensions from here to here it is d_c and from here to here it is r_2 this is d_s and from here to here r_1 and this is d_{naught} we have to find the slot area this area we have to find. So, for easy analysis we can split this area into 3 parts the first part will be in this manner and second part will be in this manner and third part will be in this manner.

So, it is a trapezoidal kind of thing. So, calculate the area for this thing this height is d_s and it is w_2 and it is w_1 . So, w_2 into d_s minus the total square area minus the 2 times the half $b h$ area the triangle area is nothing but this one this we have to remove from the square area. So, 2 into half $b h$ that is nothing but w_2 minus w_1 by 2 into d_s here 1 more by 2 will come with respect to the half $b h$ then it will results in w_2 plus w_1 by 2 into d_s and the second case here the radius is r_2 and here also r_2 and this is w_2 minus $2 r_2$ this width whatever the width is there w_2 minus $2 r_2$ calculate the area of this portion as a rectangle and this portion again arc. So, this area you just split into 3 parts this is part 1 and this is part 2 and part 3.

So, this we can write it as πr_2^2 square by 4 plus again the third point is πr_2^2 square by 4 and the second part is nothing but rectangle w_2 minus $2 r_2$ into r_2 height again. Similarly, third case also from here to here r_1 and here also r_1 this region consider it as a rectangle and calculate the area. So, if we club all these 3 terms 1 2 3 4 and 1 2 and 3 then area of the slot is nothing but final equation w_1 plus w_2 by 2 into d_s plus w_2 minus r_2 into c_1 into r_2 plus w_1 minus r_1 c_1 into r_1 this is equation number 9 here c_1 is a constant which is equals to $2 - \pi$ by 2 solve this term 1 and term 2 and term 3 with respect to the different areas then final area of the slot we will get in this manner this is the area of slot. From equation 9 and equation 4 to 8 we have to find now what is w_1 and w_2 and what is t and what is d_s all these things we have to substitute in area of the slot equation that is equation number 9. So, equation 9 involves the w_1 and w_2 and d_s and these 3 are the unknowns.

So, w_1 and w_2 and d_s we have to find equations and then we have to substitute there first we will start with w_1 that is the width of the stator slot at the bottom side. So, from the equation 7 and equation 8 we can find w_1 and w_2 just rearrange the terms from equation 7 and 8 then we can get the w_1 is equals to π by Q_s into d_i inner diameter of the stator into 2 into d_{naught} plus r_1 minus t . In this equation we know the value of t from the flux density ratios in equation 2 and 3 and 4 we have discussed the different flux densities and we have taken the ratios the t value is nothing but this one equation 4 here we can see that t value and d_c value also back iron value also that is equation 5. So, from equation 4 and 5 we can substitute the d_c value and final w_1 is nothing but π by Q_s into d_i plus 2 into d_{naught} plus r_1 minus t is nothing but d_i into π divided by Q_s into k_s steel stacking factor B_g by B_t this is the t value. Now, define B_g by B_t into 1 by k_s as a constant of G_t then w_1 is equals to π by Q_s into d_i into 1 minus G_t plus 2 into d_{naught} plus r_1 this is equation number 10.

Similarly, w_2 we have to find in terms of d_{naught} and D_i w_2 is equals to from the equation number 5 and 8 and 7 then π by Q_s into D_{naught} minus 2 into d_c plus r_2 minus t equation number 5, 7 and 8. Yeah, 8th equation is this one and 5th equation is with respect to the d_c and 7th equation is this one. So, from these three equations we have rewritten the w_2 terms and then substitute the t value as well as d_c value here. Here $2 d_c$ is nothing but 2 into D_i into B_g by B_t from the equation 4 or 5 I think this B_g by B_t value we have derived right divided by k_s into P . Here also this multiple values we can define it as a G_c some constant and already t has some constant that is t equals to D_i into π by Q_s into k_s B_g by B_t .

Here also the constant we have assumed this is G_t substitute this values in this equation and finally, we will end up the w_2 equation π by Q_s into D_{naught} minus D_i into G_t plus G_c minus $2 r_2$ this is equation number 11 with respect to w_2 . So, from equation 7 and 8 we have find the parameters right with respect to w_1 and t and D_{naught} and other things find the w_2 minus w_1 that is equals to π by Q_s or we can say directly equation 7 equation 8 minus equation 7. Then we can see the final outcome π by Q_s into D_{naught} minus 2 into d_c plus r_2 minus d_i minus 2 into d_{naught} plus r_1 . So, these terms with respect to the equation 8 and these terms with respect to the equation 7 finally, π by q_s d_{naught} minus 2 into d_{naught} plus r_1 plus r_2 plus d_c minus d_i right. So, this entire term we can replace with 2 into d_s right from the slot diagram if we will see.

So, here D_i plus d_{naught} plus r_1 plus d_s plus r_2 plus d_c all these terms if we will add 2 times to the inner diameter of the stator then we will get the outer diameter right. So, in with respect to that analysis we can get here the total term is nothing, but d_s then finally, d_s is equals to w_2 minus w_1 by 2π into Q_s this is equation number 12. Now, we have to substitute all these values in the equation 9 that is the slot area. So, slot area equation is this one substitute w_1 w_2 and then d_s value. So, slot area equation is this

one here w_1 we know w_2 we know w_1 is nothing, but equation number equation number 10 and w_2 is nothing, but equation number 12 sorry 11 and double d_s is nothing, but equation number 12.

these three equations in 9 then area of the slot is equals to w_1 plus w_2 by 2 d_s is nothing, but w_2 minus w_1 into Q_s by 2 π from the equation 12 plus remaining term I am rewriting as it is.

Let us consider this is term 1 and term 2 solve these two terms by substituting w_1 is equals to π by Q_s into d_s D_i is nothing, but inner diameter of the stator 1 minus G_t is a constant plus 2 into d_{naught} plus r_1 . This is the equation for w_1 and equation for w_2 is π by Q_s D_{naught} s minus D_i s into G_t plus G_c minus 2 into r_2 . This is with respect to the equation 10 and this is with respect to the 11 those two equations we are substituting in the area of the slot equation. At the end the term 1 in the slot area equation is nothing, but π by 4 q_s into D_{naught} s that is outer diameter of the stator square plus D_i s inner diameter of the stator square plus G_t plus G_c whole square minus 2 into D_{naught} s and D_i s into G_t plus G_c . Here G_t and G_c are the constants plus 4 r_2 square minus 4 r_2 into D_{naught} s minus D_i s into G_t plus G_c minus D_i s square into 1 minus G_t square minus 4 into d_{naught} plus r_1 square minus 4 capital D_i s into 1 minus G_t into 1 d_{naught} plus r_1 . This is the total equation with respect to the term 1.

Then term 2 this final equation will be equals to 4 π by π by 4 Q_s into D_i s square into G_t plus G_c square minus 1 minus G_c square minus 2 D_i s and D_{naught} s into G_t plus G_c plus D_{naught} s square plus r_2 square π by Q_s minus π by Q_s into r_2 D_{naught} s plus π by Q_s r_2 d_i s into G_t plus G_c minus π by Q_s into D_{naught} square plus r_1 square plus 2 d_{naught} r_1 . I am expanding the above equation. So, final equation of term 1 with respect to all terms we can see here and then term 2 is with respect to the slot dimensions that is w_1 and into r_1 minus 2 by 2 minus π by 2 into r_1 square plus w_2 into r_2 minus 2 minus π by 2 into r_2 square.

Here 2 minus π by 2 is nothing, but c_1 we have considered while discussing the slot area. Here we can see the c_1 is a constant that is 2 by 2 minus π by 2. The same thing I considered here just substitute w_1 and w_2 add term 1 that is equation number 12 and 13. So, these two equations will be 13 and 14.

Substitute 13 and 14 in slot area a_s equals to the final equation π by 4 Q_s into D_i s square that is inner diameter of the stator into G_t plus G_c square minus 1 minus G_t square minus 2 into inner diameter of the stator and then outer diameter of the stator into G_t plus G_c constants plus D_{naught} s square.

This is the equation with respect to the first term and then remaining terms with respect to the slot dimensions r_2 square into minus π by Q_s plus π by 2 minus 2 minus π by Q

s into d^2 minus r_1^2 into $-\pi Q_s^2 + 2\pi$ minus πQ_s into D_i s into d^2 into $1 - g_t$ $4 Q_s$ by π . I am multiplying to make the common bracket with respect to the total equation. Just $4 Q_s$ by π and outside π by $4 Q_s$ I am taking it common. Then final equation we can see A_s that is slot area is equals to in the form of $\pi 4 Q_s$ into f of λ plus some constant term. The second term from this point to this point, this complete term I am representing as x and from here to here I am representing as a function f of λ second order equation.

Then f of λ is equals to a_s into $4 Q_s$ by π minus x will come. So, minus x term I am replacing with plus Δ a_s into $4 Q_s$, Q_s is the number of slots by π minus x I am replacing with plus Δ . Here Δ is equals to $4 r_2^2$ square minus $2 q_s r_2^2$ square plus $8 Q_s$ by π into r_2^2 square plus $4 d^2$ minus $4 r_1^2$ plus $8 Q_s$ by πr_1^2 square minus $2 Q_s r_1^2$ square plus 4 into D_i s into d^2 into $1 - G_t$. This is the total equation for Δ it is a constant this Δ is also equals to minus x . So, this is the final equation with respect to the function f of λ .

The equation number 14 or 15 this is the equation number 15 this function represents the copper function. How much amount of copper we are utilizing in the electrical machine? Because this f of λ function depends upon the slot area number of slots and slot geometry. Slot area we have considered a number of slots and slot geometry and B_g value, B_t value and B_c value. We can see here with respect to the stator slot this is the stator lamination where we have considered the flux densities at the different parts of the core. f of λ is nothing but it is a second order equation I am representing with a λ^2 minus $2 b \lambda$ plus 1 .

Here a is nothing but G_c plus G_t^2 minus 1 minus G_t^2 b is equals to G_t plus G_c and then λ is equals to D_i by D naught s . And one more thing here we have to take it D naught s common in the this equation and f of λ into D naught s will come here D naught s square. So, this side it will be D naught s square and f of λ equals to π into D naught s square and Δ divided by D naught s square this is the final equation. f of λ final equation is nothing but A_s into Q_s divided by πD naught s square by 4 plus Δ divided by D naught s square.

This is the equation number 15. I have rewritten the equation. This equation involves the all slot geometry as well as slot area and different flux densities at different parts of the core. With this I am concluding this class. In this lecture we have discussed the D cube sizing equations where we have considered the slot geometry as well as different flux densities of the iron core like we can see here the flux densities at the back iron, flux densities at the teeth and the slot area everything we have considered to realize the sizing equations. Thank you.