

Mechanics of Machining
Prof. Uday S. Dixit
Department of Mechanical Engineering
Indian Institute of Technology, Guwahati

Lecture - 13
Tool Wear and Tool Life and Tool Life Equations

Welcome to the course of Mechanics of Machining. Today, I am going to discuss about Tool Wear and Tool Life; this is the 13th lecture in this course. What is tool wear and tool life?


(Refer Slide Time: 00:46)

TOOL WEAR AND TOOL LIFE

- Wear: failure of cutting tool due to repeated operation and loss of material from the surfaces in sliding contact
- Cause : adhesion, abrasion, erosion, surface fatigue, gross fracture, high cutting temperature

Wear process generally involves more than one type of wear

- Adhesive wear particles first form due to welding – breaking of surface asperities may oxidize and produce harder material
- Oxidized abrasive wear particles may act as solid lubricant and reduce abrasive wears



First let us discuss about the wear, wear is the failure of cutting tool due to repeated operation and loss of material from the surfaces in sliding contact. Tool is in contact with the workpiece even the chips are sliding on the rake surface of the tool. So, gradually there is loss of material that is called wear.

Wear can be caused by various reasons adhesion that actually suppose the chip is flowing on the surface. It may addle to the surface, there may be due to adhesion and after that adhesion is a type of small welding and then after that it is removed. So, it takes some material away. Suppose, there is one surface asperity is there, some this surface is not smooth, there are asperities; it may be like this, another surface is also having this type of asperities suppose they come in contact like this. So, momentarily there is a welding and

then after that, this when this separate due to force. Because, this there is a relative motion then it takes away some fragments that is basically adhesion.

Abrasion is actually caused by suppose, you have some soft material and on that top of it there is a some hard particle or hard material that abrades it; that means, because of it something like it ploughs whole material that is called abrasion. If you see the dictionary, erosion will be mentioned as one synonym of abrasion, but there is some difference there is a fine difference and that may differ from book to book also, but generally in erosion there may be some fluid material in that it may get eluded.


Suppose there is a rock and in that water is flowing. So, we say that water is eluding that but if there is a solid material, we say it is abrading that. These type of fine differences are there, but otherwise you can say people generally say abrasion and erosion combine, then, surface fatigue is there because surfaces are on contact, tool is in contact with the workpiece, there are contact forces. So, suppose tool is making contact here after that it will go away it will separate. So, this surface of the tool gets oscillating stress because suppose when this tool is actually taking large cut depth then in that case large amount of forces come on the tool, but then once it has removed that material then the force comes down also.

So, there is alternating or fluctuating force is there and because of that you will get fatigue. Then there can be gross fracture, suppose, load is force is more, then the strength of the material then tool can separate that suppose this type of tool is there, may be it can fracture like this. This portion can totally go away then of course, high cutting temperature high cutting temperature takes place that is why that tool will become soft. It will lose its hardness hot hardness and that is how that you can get this type of wear.

So, wear process generally involves more than one type of wear, one is adhesive wear particles. First form due to welding as I have told adhesive wear is very common and then they these bonds they get broken breaking of surface asperities may oxidize and produce harder material; that means, they gets broken and they get exposed and there can be oxidation and that oxidation those oxides can be actually much harder that type of thing can be there and oxidized abrasive wear particles may act as solid lubricants. Sometimes oxidized lubricants they may be brittle also and they may reduce abrasive wear also; so that means, wear is very complicated phenomena. We cannot say definitely

that what will be its effect. Usually we try to make a assessment based on some experiments; so, next.

(Refer Slide Time: 05:28)



So, suppose discuss one by one I am going to discuss. Suppose, we discuss adhesion in the cutting tool, three type of wears are very common; adhesion, abrasion and diffusion. Now, let us discuss how the adhesion wear takes place in the cutting tool. Adhesion in you can say in one word, it is basically welding and fracture of surface asperities surface is not smooth. If you see under the microscope, it may be having this type of undulations. It is not smooth, other surface is also not smooth and when the peaks of both the surfaces contact with high amount of pressure and temperature is also there..

Then, there may be at micro level there may be welding and then after that because that welded joint is not very strong it separates also. So, it causes the fracture of its surface asperities. Suppose this surface is there another surface as come in contact here they will weld here, but they will separate. So, they will in the process of separation, some material will be removed may be some material has got removed from both sides, from this material as well as from this material.

Adhesion wear may be called attritious wear, usually this we used in grinding. In grinding, we use term attritious wear, dictionary meaning is wearing away by friction. In grinding, wear of abrasive grains such that sharp edges gradually become rounded that is called attritious. It is basically you know rubbing of that and grinding due to which we

say grinding wheel becomes glazed. It looks a shining type of thing and you say that this is basically some glazing type of thing occurs. So, you will see that because these glazes are faces will become rounded and you can identify by naked eye that the grinding wheel has become glazed.


Then there is a galling, when large particles are removed that is called galling. Removed particles may stick to other surface. Second type of wear is abrasion; the scratching materials must be at least 20 percent harder. Abrasion is due to scratching. Suppose I am having some type of suppose this is wax and on which I am moving a knife. So, this knife is actually abrading the material. So, here that what happens that the scratching material must be at least 20 percent harder then, it may be caused due to ploughing, cutting and fragmentation. There is a ploughing type of phenomena; it cuts also and the chips gets fragmented means, when it is cutting then there will be fragmentation.

Then diffusion; atoms from one of the mating surface may get diffused into the matrix of the other surface depending upon relative affinity. There can be diffusion, suppose, some work material is containing carbon, it is possible that this carbon may diffuse into the tool material or vice versa. Sometimes tool is at very high temperature from the tool that some material may diffuse into the other workpiece. So, atoms from one of the mating surface may get diffused into the matrix of the other surface depending upon relative affinity that is called diffusion wear.

(Refer Slide Time: 09:27)

1) ADHESION WEAR:

- It commonly occurs in metal and depends on mutual affinity of two material.
- When two mating surfaces come in close contact, strong bonds are formed due to welding of surface asperities.
- If the bonds formed at the asperity junctions are stronger than the local strength of the material, particles may transfer from one surface to the other when the junction fracture.
- They are of two types:
 - a) **ATTRITIOUS:** The removed wear particles are very small. Gradual wear.
 - b) **GALLING:** The removed wear particles are large.



So in this case, adhesion wear is very common on the flank surface of the tool. You have flank face and rake face. Suppose I am making one tool in orthogonal cutting and it is cutting like that chip is flowing here on that; so this surface is called rake surface. As you know, rake surface is that surface on which the chip is flowing and another surface is called flank surface side, which is generally in touch with workpiece; that means, it may rub against the workpiece. So, there are 2 surfaces; this type of adhesion wear is more common in the flank face of this one.

So, when 2 mating surfaces come in close contact strong bonds are formed due to welding of surface asperities. If the bonds formed at the asperity, junctions are stronger than the local strength of the materials then particle may transfer from one surface to the other when the junction fractures. So, this one, suppose I have got this thing and if I have made a bond here, another material is this is material number 1 this may be 2 here. The bond has formed, this bond is very strong, but you applied more force because surface 2 has to move.


So, it will move, but since bond is very strong and below the bond this material is not that much strong. So, what it may do that some portion of this material it may fragment from here. And some portion of material 1 can be removed means bond will also go; so that means, you may have I am showing exaggerated, you may have this situation that this 2 component has come here, this is the bond and this surface has moved this type of material of 1 also has moved with that. So, it is really small portion of material 1.

If there are 2 types of wear adhesion wear attritious; that means, removed wear particles are very small it is a gradual wear and in galling the removed wear particles are large.

(Refer Slide Time: 11:57)

2) ABRASION WEAR:

- ▶ When two surfaces are in sliding contact, the surface asperities of the harder material plough a series of grooves on the softer material.
- ▶ The sources of hard materials are scale or sand remains during casting, wear particles etc.
- ▶ To have abrasive wear, it is necessary that one material to be harder and other to be softer.
- ▶ Abrasion wear rate depends upon the hardness, elastic properties and the geometry of the mating surfaces.
- ▶ The erosive and cavitation wear are similar to the abrasive wear.
- ▶ Scratching can be considered as the form of abrasion wear.



Then about abrasion, when 2 surfaces are in sliding contact the surface asperities of the harder material plough a series of grooves on the softer material. So that means, basically this is a soft material on that a hard material is moving like this and this is abrading; it is like this, like this, like this. So, this is making a groove if you see the if I make the top view you may observe this type of groove type of thing here.

So, the source of hard materials are scale or sand remaining during casting because we are concerned about tool wear. So, what I am telling that surface of the tool may get abraded. Who will do that? Why you say tool is very hard? Tool is harder than the work material, but then also the work material may have some constituents which will be very hard. For example, in a casting there may be some sent particles. These sent particles which were produced during casting they may abrade the tool and there may be wear particles also. They may also abrade to have abrasive wear, it is necessary that one material is harder than the and the other is softer.

So, what may happen, that may be very high temperature can rise it. When high temperature reaches, then the tool becomes soft, relatively soft and suppose you have this sand parties or anything or even the material is also suppose harder material and its temperature may not reduce that much. In fact, tool temperature may reduce more then that particular portion can be removed; that means, workpiece may contain some

constituents which may be harder than the tool, at that particular temperature and it can remove this one.


So, abrasion wear rate depends on the hardness, elastic properties and the geometry of the mating surfaces. The erosive and cavitation wear are similar to the abrasive wear. Just like abrasion, in abrasion what we mean that suppose, it is one best example is there suppose you have butter and with the knife you are moving, you are moving the slice of that. So, you are basically ploughing, I am having this material and on that I am ploughing, I am rubbing, I am moving.

Let me make correct type of figure, here, I can let me just erase these like this. See even here I may be doing some abrasion when I am moving. So, here what may happen? I have some suppose soft material and this is a tool type of thing I am just it is abrading, it is moving. It takes some cut means it plunges little bit and it is hard and it is removing so it is removing the material like this.

So, that is called abrasion, but sometimes suppose the some water fluid is moving or some chemical is moving. So, this particle may get dissolved that is generally, we call erosive wear and cavitation wear is what? You know that, cavitation sometimes occurs. Particularly, this is very common not here, but suppose in turbines, etcetera that you have some water turbine and suppose at some location, the partial pressure becomes very low. So, that water may vaporize and again, it may condense and it can condense and it can drop with a force that phenomena is called cavitation.

So, cavitation is also similar and it erodes that you know that I can have say jet of some vapor or something. So, this cavitation is also similar to that scratching can be considered as the form of abrasion wear. Suppose, we scratch we have scratcher surface scratcher is there. So, in that there is a scratcher is there that like I am doing scratching here. So, this is also a form of abrasion wear..

(Refer Slide Time: 16:45)




So, these wears are also they are and then diffusion wear that is more common on the rake surface not on the flank surface. Because, rake surface temperature is very high we have discussed in the previous class that, you get lot of temperate on the rake surface. At some distance away from the tool cutting edge; that means, from nose of the tool.

So, in diffusion wear atoms from one of the mating surfaces may get diffused into the matrix of the other surface. Depending on the relative affinity of the atoms, it causes change in physical properties such as hardness, toughness, ductility, diffusion is a time and temperature dependent phenomena, it depends on the time of contact more there is a contact more will be the diffusion, diffusion is a process which is dependent on the time and also it is dependent on temperature. Diffusion is basically a type of chemical process when one constituent will enter into the other because of the concentration difference.

So, it is accelerated usually by temperature at high temperature more material will diffuse. So, it occurs due to high interface temperature between tool and the workpiece during machining due to high temperature the atoms from hard material get diffused to the softer material. And the mechanical properties hardness ductility and toughness get changed.

So, they get diffused to the so what happens, that tool is suppose very hot hard, but it is hard and from there it may get diffused into the workpiece. And therefore, tool may become weak that type of thing may happen.

(Refer Slide Time: 18:42)



Now, so progressive tool wear what do we mean by progressive tool wear; that means, wear is increasing with time. So, I have made a schematic diagram here this is the workpiece and this is a cutting tool and this is doing cutting suppose workpiece is coming in this direction. So, material is removed in the form of the chips as you can see that the chip is rubbing against the rake surface and maximum temperature may be somewhere here on this surface in this one. So, 2 type of wears are very common one is the flank wear on the flank surface. This material some wear may take place and therefore, this is the wear and may be this much material gets removed ultimately this portion comes.


So, flank wear will affect the dimension because, as you can see that suppose this portion has come in contact and. Therefore, that what happens that instead of this much surface now this one is there. So, it is basically effectively that distance from this one has increased suppose here you are getting this type of surface, but suppose this material has been removed. So, now, the tools location is land this one. So, this nose basically has shifted from here to here because that much. So, new geometry is this because the bottom portion has worn out so; that means, effectively now earlier the depth of cut was from here to here now the depth of cut is from only here to here.

So; that means, you basically get dimension. So, dimension is stability is effected by means of flank wear and this is this much material has been removed from here to here

and this portion has come in contact. Now, so this is called wear land L_w is the wear land on the other hand crater wear takes place on the rake surface here you get a crater type of thing; that means, a pit type of thing like this type of pit some material. So, crater wear occurs here crater wear will not affect the dimensional stability because crater is on this surface, but dimensional accuracies effected by this one, but crater may change effective rake angle and how and it generally makes the tool very big.

Suppose this much crater, crater has been created you see that here this much material is only left. So, the tool has become very weak. So, flank wear is the wear taking place on the flank face of the tool and crater wear is the wear taking place on the rake face of the tool like crater or pit this is called crater wear.

(Refer Slide Time: 21:55)



Flank wear is usually evaluated in terms of the length of the wear land which can be measured by means of a measuring microscope. We can see it on a tool makers microscope so this is flank wear land from here to here. If you say material has been removed and wear and growth can be divided into 3 regions. We can make time versus flank wear to initially the wear is very rapid. Why because on the surface there may be already some asperities which are actually very high may be 1 or 2 and in a regular way. So, what will happen that they will get warm soon, but once they have become worn then more or less you get relatively flat structure. So, now, the wear will be small. So, initially there is some (Refer Slide Time: 22:55) period in which the wear rate is very fast then

there will be steady wear zone which is for a longer duration. And after some time the tool will become very weak and then there will be severe wear zone that will be very rapidly causing tool to fail.


So, initial wear zone; that means, sharp cutting edge of the tool is quickly broken down suppose tool is there it is having very sharp cutting edge. In beginning then it will produce large amount of stress also because these stress are force divided by area. So, that sharp cutting edge will experience lot of stress and it will be getting broken or fractured or it will deform here. Then what happens that remain suppose this much small portion gets. So, it automatically will become rounded type of thing and contact area will increase. So, now, further wear will reduce.

So, in the beginning sharp cutting edge of the tool is quickly broken and wear rating this region is high. Since, the area of contact is less that is the initial tool wear zone this figure is not to the scale. Actually, this region may be very small and this region can be very bigger actually middle region then we have got steady wear zone in that experiment show that normal force on the cutting tool is proportional to the size of wear land. So, it is generally proportional to the normal force and land growth curve is usually be linear and wear increases that uniform rate then we have got severe wear zone; that means, wear rate is high because of high temperature plastic deformation.

When lot of wear has taken place more wear has taken place more area is in contact. Suppose, even the tool was very nicely doing its job in the beginning and it was having something like this type of shape. Not much portion was in contact, but after some time when the material has worn then, there will be more contact just like suppose you have got suppose some tyre. It is a brand new tyre it will be having contact at point and then after that suppose tyre gets worn out then it will be more surfaces will be in coming in contact and therefore, this temperature will increase further and high temperature. You will be getting and then the wear rate will be very rapid in this case.

So, finally, that wear rate is very high and generally it is seen that the wear land is proportional to F_q particularly in steady wear zone. So, F_q is may be the force normal force coming on the tool

(Refer Slide Time: 25:58)




We did some experiments actually with time and wear we are measuring the wear up to now, we have taken one condition in which cutting speed was 135 meter per minute. These were called wipe tools feed was point 3 2 mm per evolution depth of cut was point three mm and we got this type of curve c we have got very small here the wear is very rapid, but then more or less. It is steady wear rate is not very high and we did only up to this, we got a wear of about less than 0.18 or something, but here the second case you have velocity cutting speed of 270 meter per minute, speed of 0.32 meter per evolution and depth of cut was 1.2.

So, more severe condition so here the wear rate was very high very rapid and you are having that here you see up to that, about I think more than 0.6 or something like 0.6 up to 0.6 or 0.7. That you just see no if you draw may be 0.6 is up to here. Only and this may be 0.7. So, between 0.6 to 0.7 somewhere that much wear has taken place and naturally the tool is considered to be fail many people take this as a criteria that this much amount of wear land as tool rate if the wear land is beyond that then naturally it has to be tool has to be changed.

So, I just showed these 2 figures to illustrate that how the cutting conditions affect the flank wear.

(Refer Slide Time: 27:46)



Now, what about crater wear? Crater wear is evaluated in terms of the depth of crater and the shape is assumed to be segment of an arc; that means, basically it is usually will occur on the rake surface of the tool. Suppose, this is the tool this is nose and this is rake surface and here I get crater type of thing I plot a crater this much; that means, this is we you have got a crater let me erase that upper portion yes up to this; that means, now the tool has become like this we got a we got a crater type of thing just like we get a pit in the road. Pothole type of thing we get that type of crater we will be getting and it is evaluated in terms of the depth of crater;.

That means, we say how much is the depth of the crater from here to here and the shape is assumed to be circular at low cutting speed the cutting is protected from the action of the chip because of the formation of a stable built up edge at low cutting edge speed already there is built up edge.

So, chip will slide on the top of the built up edge and there may not be contact of the chip with the rake surface. So, we do not get crater, but at high cutting speed diffusion plays a major role why because the at high cutting speed temperature also becomes high. Because, more power is there that gets in converted into heat. So, maximum temperature at the chip tool interface appears to exist at some distance from the tool edge not at the tool edge maximum temperature is not here rather it is here why it is here because already some heating was done because of the plastic work then on top of that chip is

sliding and the chip is sliding. So, its temperature is again increasing. So, it may be somewhere here maximum temperature that is why maximum amount of crater wear is here.

At higher speed the crater wear is predominant than flank wear because diffusion is a temperature sensitive phenomena it occurs at high velocity tool chip interface. So, generally it will occur on this one now having talked about the flank wear and crater wear.

(Refer Slide Time: 30:28)

TOOL LIFE

- A tool that no longer performs the desired function is said to have failed.
- The tool life can be defined in following ways:
 - Cutting time to failure
 - Cutting length to failure
 - Volume of material removed to failure
 - Number of components produced to failure

Various ways in which tool failure can be identified

Wear land size, depth of crater, tool wear volume, magnitude of cutting forces, surface finish value, change in component size, total destruction of tool

VARIABLES AFFECTING TOOL LIFE

- a. The cutting conditions
- b. The tool geometry
- c. The tool material
- d. The work material
- e. The cutting fluid


Which are the 2 common wear in which of course, as I told dimensional stability or dimensional accuracies affected by flank wear and rake angle is affected by top rake angle? By crater wear even side rake angle also will be affected by crater wear.

So, tool life we should discuss now a tool life is what a tool that no longer performs the desired function is said to have failed; that means, we say tool life failed tool life can be defined in many ways. One is cutting time to failure like after 5 minutes of machining. My tool failed then we say that tool life is 5 minutes cutting length to failure that how much meter it has moved so; that means, cutting length or volume of material removed to failure; that means, before failing. How much volume it has removed and the number of components produced to failure. We can do like that if there are similar type of components we can say this tool made about hundred components other tool made 150.

So, one tool's life is 100 pieces, others is 150 pieces, but cutting time to failure is most common tool life. Various ways in which tool failure can be identified; first we have some criteria about wear land size. Say for example, we say HSS tool is there and we say if the wear land is more than 0.4 mm. Then we will say tool has failed and we will change the tool. So, wear land size is there, depth of crater can be there, some criteria tool wear volume we can measure, magnitude of cutting forces; that means, we can also say tool life like this that if the cutting forces will increase then we will say the tool life is means is 1; when the tool life will be over the forces will increase to a large extent.

Then, surface finish value suppose we are not now getting the good surface finish. In the beginning, surface finish was good, but now the surface finish has become poor then also this one change in component size the suppose lot of flank wear is there you are doing the same type of setting, but now you see that your component is of slightly increased size; that means, some wear has taken place and total destruction of the tool sometime catastrophic failure can also be there; that means, tool can be tool can get broken variables effecting tool life are cutting conditions what is the feed depth of cut and cutting speed tool geometry is one feature then tool material and then the work material and whether we are using cutting fluid or not because cutting fluid does some lubrication so may be the tool life is improper.

(Refer Slide Time: 33:38)




Cutting condition means experimentally it is found at the rate of wear increases as cutting speed is increased. The wear land-cutting time curves are obtained at various cutting speeds. Suppose this is the at V_1 is less cutting speed, V_2 is more, V_3 is the highest cutting speed in this figure. And this is the wear land and this is cutting time. So, we are seen that here at low cutting speed, first you are having some initial wear period. Then steady wear period and then high wear period rapid wear period, but this wear is nevertheless less. If the cutting speed is increasing, then the wear is increasing. And similarly if the cutting speed has increased further then wear rate has increased further and overall life has reduced.

From such curves, we obtain 2 life at various cutting speeds for a critical wear land size L_w can be obtained. I may have some criteria. So, my critical wear may be L_w^* , when L_w^* wear will take place I stop my machining operation and change the tool. So, you see that L_w line was cutting this curve here at this point. So, at V_1 the tool life is T_1 , at V_2 the tool life is T_2 and at V_3 the tool life is T_3 . Taylor did these type of experiments basically, in the something last decades of this one 19th century; that means, before something like 1900 and he has done lot of experiments F W Taylor. And he machined several materials and got lot of data and that he has in fact, he has tons of material I think he machined.

So, he gave and this a study he conducted for about decade and then he obtained this type of Taylor tool life equation that is $V T^n = C$, where V is cutting speed, T is tool life, n and C are constants. So, V is cutting speed, T is tool life and n and C are constant which depend on the tool and workpiece combination; this is called Taylors tool life equation.

(Refer Slide Time: 36:20)



I can plot it on log plot I take plot here $\log v$ and $\log n$, then I am getting a linear type of curve and the slope of this one is basically $1/n$; means $\tan \theta$ is equal to basically $1/n$.

So, this we can find out if we can conduct plot of experiment we can plot this type of curve then we can find out exponents also. So, this equation one can use.

(Refer Slide Time: 36:53)

- The variables speed, feed and depth of cut, affect the material removal rate and hence have a direct bearing on the production cost. The above equation can be rewritten to show the effect of cutting speed as:

$$T = \frac{C^{1/n}}{V^{1/n}} \quad (2)$$

- Tool life can also be expressed as:

$$T = \frac{C_1}{V^{1/n} f^{1/n_1} d^{1/n_2}} \quad (3)$$

where

- f = feed
- d = depth of cut,
- C_1 = constant for a given tool-work material combination and tool geometry, and
- $1/n_1$ and $1/n_2$ are the exponents for feed and depth of cut, respectively.

- Here $1/n > 1/n_1 > 1/n_2$ and indicates that the cutting speed has the greatest influence on tool life followed by feed and then depth of cut.

The variables speed and depth of cut affect the material removal rate and hence have direct bearing on the production cost. The above equation can be rewritten to show the

effect of cutting speed as tool life T is equal to C_1 to the power n divided by V to the power $1/n$. So, you can see that if n is very small then, we will have more effect much more effect on that one, but suppose n is very large then it may not have that much effect.

So, tool life can also be expressed as T is equal to $C_1 V^{1/n} f^{1/n} d^{1/n}$ or sometimes we say V and may be f to the power something x and d to the power y and t to the power n is equal to constant; this type of thing, no matter in what way you express. Here, it has been expressed in this way T is equal to C_1 by this one, but or you can express in this way, but this is called Taylor's extended tool life equation. It is showing the effect of f and d also. If f increase then also tool life decreases if d increases then also T life decreases, but effect of these speed is more; that means, in this expression $1/n$ is much more than $1/n$ and it is much more than $1/n$. So, it indicates that the cutting speed has greatest influence on tool life followed by speed and then depth of cut. So, therefore, what you should do? That you should try to take as much depth as possible and then you can have more speed also, but try to have the cutting speed somewhat small.

(Refer Slide Time: 38:56)

- Tool life is related to cutting temperature irrespective of the cutting condition by a relationship of the form

$$T\theta^m = C_2 \quad (4)$$


In general the cutting temperature will increase with V , f and d and hence the effect of these variables can be combined in terms of temperature

15

Now, tool life is related to cutting temperature irrespective of the cutting condition. Means whatever effect is there, cutting speed effect or speeds effect ultimately generates some temperature and we can also like this type of equation. That $T\theta^m$ to the power

m is equal to C 2. In general, the cutting temperature will increase with V, f and d and hence the effect of these variables can be combined in terms of temperature.


(Refer Slide Time: 39:25)



Now, let us see that what is the effect of the tool geometry rake angle, what is the effect of the rake angle? If we increase the rake angle, then the cutting force reduces and the cutting temperature also reduce because of that. So, it results in increase tool life, but when the tool rake angle is very large although the cutting forces are lower. The tool edge is weakened resulting in increased failure to chipping of the cutting edge. So, that is why that if the rake angle in the suppose, there is tool like this its rake angle is this if I increase the rake angle; that means, this surface really has come here then in that case you see the tool has become weak. Earlier, this much thickness was there here now this thickness is this much only.

So, that is why tool edge will be weakened and it will result in increased failure chipping of the cutting edge. Hence, there is optimum, there is an optimum rake angle which gives the maximum tool life. So, that is why you are seen that the tool life is first increasing with rake angle and then it is starts decreasing. So, there is an optimum tool angle.

(Refer Slide Time: 40:41)



Rake angle same thing happens about flank angle or clearance angle. Here, that cutting tool is there and this is the flank surface this is the surface which is machined there is some gap between machine surface and this.

Now, if I have it very less then there will be rubbing between the workpiece and tool there may be some even if we set it to like there is a clearance here, but because of the heating there will be expansion. So, this portion will stop touching the tool here these type of. So, therefore, you have to have sufficient gap so there may be rubbing between the tool and the workpiece and hence if you increase the flank angle.

Then, it will reduce the rubbing between the tool and the workpiece and hence it will improve the tool, but life, but again if you increase the flank angle too much, again tool gets weakened. Because, suppose I am showing that suppose this is like this. Now you want to increase this one flank angle, then you may make a tool like this, but this tool is thinner.

So, optimum value of flank angle is also affected by the feed rate higher the feed rate lower is the optimum value. So, here it is this one here the optimum flank angle here is this, but if the here f_1 is more much more and this is less. So, that is what it is happening; f_1, f_2, f_3 , f_1 is the highest. So, you are having optimum flank angle is less.

(Refer Slide Time: 42:23)

SIDE CUTTING EDGE ANGLE

- For a given feed and depth of cut, the length of the engaged cutting edge increases with increase in the side cutting-edge angle.
- This gives lower cutting temperature and increases the tool life.




Fig. 9 Effect of side cutting-edge angle on tool life for work materials of different flow stress

18

Side cutting edge angle for a given feed and depth of cut the length of the increase engaged cutting edge increases with increase in the side cutting edge angle. This gives lower cutting temperature and hence increases the tool life. So, side cutting edge is also having this type of behavior.

(Refer Slide Time: 42:43)

NOSE RADIUS


- A nose radius on the tool is favorable for long tool life.
- A nominally sharp tool is highly stressed at the tip and has short tool life.
- An increase in nose radius, therefore, improves the tool life.
- Increase in nose radius also increases the cutting forces and is conducive to chatter.
- From these considerations nose radii in the range of 0.5-2.5 mm are used most often.

19

And nose radius nose radius on the tool is favorable for long tool life suppose nominally sharp tool is highly stressed at the tip and has sharp tool life increase in nose radius. Improve the tool life increase in nose radius also increases the cutting forces and is

conductive to chatter. So, therefore, you have to have here also some optimum nose radius and that is generally kept between 0.5 to 2.5 mm these type of we keep.

(Refer Slide Time: 43:15)



TOOL MATERIALS

1. Hot hardness:- Maintaining hardness at elevated temperatures.
2. Tough enough to withstand shock and fracture.
3. Should have high resistance to wearing action.
4. Coefficient of friction should be low.
5. Thermal conductivity and specific heat should be high.
6. Thermal expansion should be low
7. Easier in fabrication and cheap in cost

- A wide variety of cutting tool materials are still in use and the common ones are:
 - a) Carbon tool steel
 - b) High-speed steel
 - c) Cast non-ferrous alloys
 - d) Cemented carbides
 - e) Sintered oxides
 - f) Artificial abrasives
 - g) Diamond.

Now, what are the properties of the tool materials, very important is the hot hardness; that means, it should retain its hardness at high temperature, then it should be tough; that means, it should be able to withstand shock and fracture it should have high resistance to wearing action. It should have coefficient of friction should be low its thermal conductivity and specific heat should be high thermal expansion should be low it should be easy to fabricate and cheap in cost.

Wide variety of cutting tool materials are still use and common ones are carbon tool steel basically high carbon tool steel. Then high speed steel then cost non ferrous alloys then cemented carbide sintered oxide and artificial abrasives we can have diamond also.

(Refer Slide Time: 44:09)

- **Carbon tool steel**:- Contains 0.9 to 1.2% carbon and some alloying elements. High carbon steel has 0.9% C + 0.6% Mn + rest Fe – **little use in today**
- **High-speed steel (HSS) are alloy steels**:- Mainly consisting of about 18% tungsten, 4% chromium, 0.75% C, 0.6% Mn and 1% vanadium
- **'Moly'HSS**:- **tungsten is partially replaced by molybdenum**
• 8% molybdenum, 4% chromium, 1.5% tungsten, 0.6% Mn and 1% vanadium.
- **Super HSS**:- 12% cobalt is added for better hot hardness and resistance to abrasion with some sacrifice in toughness.
- **Cast non-ferrous alloys** :- 43-48% cobalt, 17-19% tungsten, 30-35% chromium and about 2% carbon.

Carbon tool steels will contain generally, carbon in the range of 0.9 to 1.2 percent and some alloying element. It may have manganese and this one small amount of sulphur is also there, but not much used in industry nowadays. High speed steel usually they contain suppose 18 percent tungsten, 4 percent chromium and 1 percent vanadium. This type of steel is called 18 41 and there is some carbon and manganese also there.

Molybdenum HSS is basically tungsten is replaced by molybdenum. So, we have 8 percent molybdenum, 4 percent chromium, 1.5 percent tungsten, 0.6 percent Mn and 1 percent vanadium. Super HSS; Super High Speed steel 12 percent cobalt is added to better hot hardness and resistance to abrasion with some sacrifice and toughness. Cast non ferrous alloy can be 43 to 48 percent carbon, 17 to 19 percent tungsten, 30 to 35 percent chromium and about 2 percent carbon.

(Refer Slide Time: 45:24)

- **Cemented carbides or sintered carbides:-**
 - Composed of hard metallic carbides bonded together in a metallic matrix.
 - The main ingredients in most common cemented carbide tools are tungsten carbide and cobalt binder.
 - Sometimes titanium or tantalum carbides are added to reduce cratering wear.
- **Sintered alumina:-** Containing about 90% sintered aluminium oxide + Boron Nitride powders.
- **UCON:-** Consists of 50% columbium (niobium), 30% titanium and 20% tungsten and permits 60% increase in cutting speed when compared with tungsten carbide.
- **CBN (Cubic Boron Nitride):-** It has five times more tool life than carbides. Hardness is next to diamond. Generally used for grinding purpose
- **Artificial abrasives:** Artificial abrasives and diamond are used for grinding and polishing purposes only and their use in metal machining is limited.
- **Coated carbide** with thin film of TiC / TiN on cemented carbide tool

22

Cemented carbides or sintered carbides are very much in use they are composed of hard metallic carbides like tungsten carbides bonded together in a metallic matrix. Main ingredients in most common cemented carbide tools are tungsten carbide and cobalt binder. Sometimes titanium or tantalum carbides are added to reduce crater wear sintered alumina containing about 90 percent sintered alumina oxide plus boron nitride power union carbide developed some UCON. It consists of 50 percent columbium thirty percent titanium and twenty percent tungsten and permits 60 percent increase in cutting speed.

Cubic boron nitride expensive tool, but it has five times more tool life than carbides hardness is next to diamond. Generally, used for grinding purpose artificial abrasives and diamonds are used then coated carbide are there in which we put a thin film of tic or titanium nitride on cemented carbide tool.

(Refer Slide Time: 46:37)

➤ Coated carbides are used for countering crater formation.

- A thin film of about 0.005 mm of TiC when deposited on cemented carbide tools reduces crater formation.
- Other coatings are Al_2O_3 and TiN.
- TiC and Al_2O_3 provide chemically stable layer between chip and tool
- TiN provides low tool friction.
- Multi-layer coatings of TiC and TiN have been used.
- In this arrangement, the stable diffusion barrier is provided by TiC, which prevents iron from entering the cobalt phase, and carbon from leaving the carbide substrate, while TiN provides low chip-tool interface friction.



23

So, coated carbides are used for countering crater formation a thin film of about 0.005 mm; that means, 5 micron of tic when deposited on cemented carbide tools reduces crater formation. Other coatings are Al_2O_3 and tin tic and Al_2O_3 provide chemically stable layer between chip and tool. Tin provides low tool friction multi-layer coatings of tic and tin have been used in this arrangement the stable diffusion barrier is provided by tic and then tin provides low chip tool interface friction.

So, what happens that suppose the coating I will do like this, that here suppose this is my tool this is the rake surface. So, here first I will coat tic and on top of that I will coat this one will be this is not up to the scale, but I am just showing tin. So, tin portion will come in contact with the chip. Whereas, tic portion is in contact with this side. So, this is what this type of thing you can do and.

(Refer Slide Time: 47:55)

- The most desirable property of a tool material for machining purposes appears to be high hot hardness.
- An increase in hardness, however, decreases the toughness or fracture strength. Further, harder the material, more difficult is the problem of giving it the required shape and geometry.

➤ Figure 9 shows the effect of temperature on the hardness of typical tool materials.

➤ High-speed steels, for example, are good about 600 °C, beyond which the hardness drops rapidly.

➤ Carbon tool steels, on the other hand withstand very low temperature, hence are good for cutting at low speeds only.




Fig. 10 variation of tool hardness with temperature (a) Carbon steel (b) High speed steels (c) non-ferrous cast alloys (d) cemented carbides (e) sintered oxides

24

The most desirable property of a tool material for machining purpose appears to be high hot hardness.

An increase in hardness decreases the toughness and we see the graph that with temperature the hardness is decreasing. So, high speed steel or good about 600 degree centigrade up to that. So, these type of for various type of tool materials these graphs have been plotted

(Refer Slide Time: 48:23)

Sintered carbide & cemented oxides retain their hardness at elevated temperature also and hence are suitable for use cutting speeds.

It has been found experimentally that the value of exponent n is higher for harder material.

Thus, the effect of cutting speed on tool wear and tool life will be greater when softer materials are used.

$$VT^n = C$$

25

And then it has been found experimentally that the value of exponent n in Taylor's tool life equation is higher for harder tool material; that means, $V T^n$ is equal to constant and this one.

(Refer Slide Time: 48:40)

WORK MATERIALS

- In general, harder the work material, higher will be the tool wear rate and lower will be the tool life
- Experimentally, for a constant tool life, the work material hardness and cutting speed are approximately related by an equation of the type:

$$V_T = \frac{C'}{H^{n'}} \quad (5)$$

Where

- V_T is the cutting speed for a given tool life,
- C' and n' are constants and
- H is the hardness on material.

26

And then generally that hardness of the material also effects the tool wear; that means, corresponding cutting speed for a given tool life will reduce of the hardness is more.

So, we can have such this type of some equation approximate equation.

(Refer Slide Time: 48:57)

CUTTING FLUIDS:-

- Used for decreasing the cutting temperature and the chip-tool interface friction
- They also cool the workpiece to avoid thermal expansion
- Promote easy handling
- Provide a rust-proof layer of the finished surface and remove chips from the machining area
- Cutting fluids are either oil based or water-based

Cutting fluids are used for decreasing the cutting temperature and the chip tool interface friction. They also cool the workpiece to avoid thermal expansion and they promote easy handling they provide a rust proof layer of the finished surface. And remove chips from the machining area cutting fluids are either oil based or they are water based.

(Refer Slide Time: 49:22)

- Oil-based fluids are generally effective in reducing friction in low-speed cutting operations such as tapping, broaching, etc.
- The mode of lubrication is one of boundary lubrication and the chemical property of the cutting fluid is more important than its physical properties
- At high cutting speeds, oil-based cutting fluids are ineffective and it is the cooling action that is operative
- The water-based fluids are, therefore, more effective at high cutting speeds because of their high specific heat and conductivity

28

Oil based fluids are generally effective in reducing friction in low speed cutting operation such as tapping and broaching etcetera. Now, mode of lubrication is one of boundary lubrication and the chemical property of the cutting fluid is more important than physical properties at high cutting speed oil based cutting fluids are ineffective and it is the cooling action. That is operative water based fluids are therefore, no effective at high cutting speed because of their high specific heat and conductivity because they have to quickly dissipate heat.

Now, let us see that how we determine tool life equation 1 way is that you conduct large amount of experiments at different.

(Refer Slide Time: 50:11)

DETERMINATION OF TOOL-LIFE EQUATIONS

- In order to evaluate tool-life constants n and C of equation, cutting tests are carried out on a lathe at a suitable feed rate and depth of cut.
- Tool-life values for a critical wear-land size can be obtained and plotted on logarithmic co-ordinates to obtain the values of n and C graphically
- Alternatively, the exponent n can be evaluated from the relationship

$$n = \frac{\log \left(\frac{V_b}{V_a} \right)}{\log \left(\frac{T_a}{T_b} \right)} \quad (6)$$

where

- V_a and V_b are any two cutting speeds and
- T_a and T_b are the corresponding tool life values

29

Temperature different cutting speed and then you can get you can plot, but what happens in order to evaluate tool life constants n and C of equation cutting tests are carried out, but you cannot effort to waste lot of material in conducting the test. So, some efficient ways has to be found out tool life for a critical wear land size can be obtained and plotted on logarithmic coordinate to obtain the values of n and C graphically and exponent can be evaluated. From this relationship also, n is equal to $\log V_b$ by V_a $\log T_b$ T_a by T_b . Where, V_a and V_b are any 2 cutting speed and T_a and T_b are corresponding tool life values.

(Refer Slide Time: 51:00)

- Experiments indicate that typical values of n for common tool materials are :

| Tool Material | Value of n |
|-------------------|--------------|
| HSS | 0.1 to 0.15 |
| Cast alloys | 0.15 to 0.2 |
| Cemented carbides | 0.2 to 0.5 |
| Sintered oxides | 0.5 to 0.8 |

30

We can do that and experiments have indicated for HSS we got 0.1 to 0.15 cast alloys n was 0.15 to 0.2 cemented carbide. It was 0.2 to 0.5 sintered oxides was 0.5 to 0.8.

(Refer Slide Time: 51:17)

QUICK TOOL LIFE TESTING

- The tests include
 - facing tests,
 - taper turning tests and
 - disc turning tests
- In facing test:
 - The tool traverses radially outwards from diameter D_1 to D_2 thereby changing the cutting speed continuously from V_1 to V_2
 - The effect of variable speed is evaluated in terms of an equivalent cutting speed V_{eq}

Which is constant speed and give the same tool wear in the same cutting time as the variable speed

- Assuming linear wear-land growth as approximated in Figure 11.


$$\frac{dl_w}{dT} = \frac{\text{Flank wear land } (l'_w)}{\text{tool life}(T)} \quad (7)$$

31

Now, quick tool estimation methods are like that one method is based on facing test, other is taper turning test. And the third is the disc turning test in facing test what we do tool traverses radially outward from diameter D_1 to D_2 . There by changing the cutting speed continuously from V_1 to V_2 . So, cutting speed is continuously changing it is not a constant speed I will put a tool here and the tool will start moving like this. So, it will do facing you know facing operation.

If I show the other view it is a circle and this face will be machined. So, effect of variable speed is evaluated in terms of equivalent cutting speed which is constant speed and give the same tool wear in the same cutting time as the variable speed you assume there is linear wear land growth because steady wear zone you have seen that wear land is proportional to time. So, we say dl_w by dT is equal to flank wear land l'_w by tool life this equation is there you can use.

(Refer Slide Time: 52:31)



And then we have we conduct tool life testing like this wear land size l_w and criteria for flank wear land and this is what you see that it is linear.

(Refer Slide Time: 52:44)

- If Taylor tool-life equation is assumed to hold in the range of cutting speed covered while the tool travels from diameter D_1 to D_2 , the wear land l_{w1} at any time T_1 can be obtained as

$$l_{w1} = \int_0^{T_1} \frac{l_w^*}{C^n} V^{\frac{1}{n}} dT$$
- Since equivalent speed V_{eq} will also give the same flank wear land l_{w1} after time T_1

$$l_{w1} = \frac{l_w^*}{C^n} V_{eq}^{\frac{1}{n}} T_1 \quad (8)$$
- The corresponding equivalent speed V_{eq} after equating the l_{w1} above

$$V_{eq} = \left[\frac{1}{T_1} \int_0^{T_1} V^{\frac{1}{n}} dT \right]^n \quad (V_{eq})^{\frac{1}{n}} T_1 = \int_0^{T_1} V^{\frac{1}{n}} dT \quad (9)$$

33

So, here if Taylor tool life equation is assumed to hold in the range of cutting speed covered while the tool travels from diameter D_1 to D_2 , D_2 is more than D_1 , the wear land l_{w1} at any time T_1 can be obtained by this formula; l_{w1} 0 to T_1 and we have $l_w = C^n V^{\frac{1}{n}} dT$. Since, equivalent speed V_{eq} will also give the same flank wear land after time T_1 then we get this type of relation, l_{w1} is actually this. So, if we make the

correspondence between these 2 we get, V equivalent is equal to 1 by T1 0 to T1 V to the power 1 by n dT to the power n and we are getting this type of relation.

(Refer Slide Time: 53:36)

- If Taylor tool-life equation is assumed to hold in the range of cutting speeds covered while tool travels from diameter D_1 to D_2 , the wear land l_{w1} at any time T_1 can be obtained as:

$$\int_0^{l_{w1}} dl = \int_0^{T_1} \beta dT \text{ where } \beta \text{ is slope}$$

The constant slope is estimated from the condition given in figure 11

$$l_{w1} = \int_0^{T_1} \frac{l_w^*}{C^n} V^{\frac{1}{n}} dT$$

$$at l = l_w^*, T^* = \frac{C^{1/n}}{V^{1/n}}$$

$$\text{slope } \beta = \frac{l_w^*}{T^*} = \frac{l_w^*}{C^{1/n}} = \frac{l_w^* V^{1/n}}{C^{1/n}}$$
- The corresponding equivalent speed V_{eq}

$$V_{eq} = \left[\frac{1}{T_1} \int_0^{T_1} V^{\frac{1}{n}} dT \right]^n \quad (V_{eq})^{1/n} T_1 = \int_0^{T_1} V^{\frac{1}{n}} dT$$
- Since equivalent speed V_{eq} will also give the same flank wear land l_{w1} after time T_1

$$l_{w1} = \frac{l_w^*}{C^n} V_{eq}^{\frac{1}{n}} T_1$$

If Taylor tool life equation is assumed to hold in the range of cutting speeds covered while tool traverse from diameter D_1 to D_2 , the wear land l_{w1} at any time can be obtained like that $\int_0^{l_{w1}} dl = \int_0^{T_1} \beta dT$, where, the β is the slope and the constant slope is estimated from this. So, we get l_{w1} is equal to this one and at $l = l_w^*$, T^* is equal to this much and slope $\beta = \frac{l_w^*}{T^*}$ that can be written as $l_w^* = \beta T^*$ by Taylors tool life equation $VT^n = \text{constant}$. So, T^* can be written like this and you get this equation. So, corresponding equivalent speed comes out to be this one. Since equivalent speed will also give the same flank wear land l_{w1} after time T_1 , so, we get l_{w1} is equal to this much..

(Refer Slide Time: 54:40)

- In facing tests the cutting speed varies with diameter and time as

$$V = 2\pi RN = 2\pi N(fNT + R)$$

Where

N = spindle speed,

f = feed per revolution and

T = cutting time to reach radius R

- From equations (9), the equivalent speed V_{eq} in facing from radius R_1 to R_2 in time T_1 can be obtained as

$$V_{eq} = \left[\frac{1}{T_1} \int_0^{T_1} V^n dT \right]^{\frac{1}{n}} = 2\pi N \left[\frac{1}{T_1} \int_0^{T_1} (fNT + R_1)^{\frac{1}{n}} dT \right]^{\frac{1}{n}} = \pi N \left[\frac{n}{n+1} \left(\frac{D_2^{\frac{1+n}{n}} - D_1^{\frac{1+n}{n}}}{D_2 - D_1} \right) \right]^{\frac{1}{n}} \quad (10)$$

$$T_1 = \frac{R_2 - R_1}{fN} = \frac{D_2 - D_1}{2fN} \quad (11)$$

35

And then if you equate in facing test the cutting speed varies with diameter and time as this one V is equal to $2\pi RN$; R is the radius and $2\pi N$ and this is fNT plus R_1 , f is feed per revolution and this one.

So, here equivalent speed in facing from radius R_1 to R_2 in time T can be obtained by putting these values and integrating then you will get equivalent speed and you get T_1 is equal to this much R_2 minus R_1 D_2 minus D_1 by this one. So, you can obtain this one.

(Refer Slide Time: 55:27)

- For a given D_1 and D_2 , $V_{eq} \propto N$ and the effect of cutting speed on tool life can be obtained by varying N
- The fraction of tool life X consumed in time T_1 when tool moves from D_1 to D_2 is

$$X = \frac{1}{C^{\frac{1}{n}}} V_{eq}^{\frac{1}{n}} T_1$$

$$X = \left(\frac{\pi N}{C} \right)^{\frac{1}{n}} \left[\frac{n}{n+1} \left(\frac{D_2^{\frac{1+n}{n}} - D_1^{\frac{1+n}{n}}}{2fN} \right) \right] \quad (12)$$

$$l_{w1} = \frac{l_w^*}{C^{\frac{1}{n}}} V_{eq}^{\frac{1}{n}} T_1$$

$$i.e. \frac{l_{w1}}{l_w^*} = \frac{1}{C^{\frac{1}{n}}} V_{eq}^{\frac{1}{n}} T_1$$

36

For a given D_1 and D_2 , V equivalent is proportional to N and the effect of cutting speed on tool life can be obtained by varying N . So, fraction of tool life consumed in time T_1 , when tool move from D_1 to D_2 is X is equal to this much and X is equal to πN by C and this one. You can substitute these values equivalent speed, $1 w 1$ is equal to this much, this is also is given here.

(Refer Slide Time: 55:59)

- If X_1 and X_2 are the fraction of tool life consumed at spindle speed N_1 and N_2 for a given D_1, D_2 and f then:

$$\frac{X_1}{X_2} = \left(\frac{N_1}{N_2} \right)^{\frac{1-n}{n}} \quad (13)$$

$$n = \frac{1}{\left[\log (X_1 / X_2) / \log (N_1 / N_2) \right] + 1} \quad (14)$$

$$C = \pi N \left[\frac{n}{n+1} \left(\frac{D_2^{\frac{1+n}{n}} - D_1^{\frac{1+n}{n}}}{2 f N X} \right) \right]^n \quad (15)$$

- Thus, by performing tests at two different speeds N_1 and N_2 for a set of diameters D_1 and D_2 , the tool life constants C and n can be evaluated

If X_1 and X_2 are the fractions of tool life consumed at spindle speed N_1 and N_2 for a given D_1, D_2 and f , then X_1 by X_2 is equal to this much.

So, if we put these things ultimately we can get n is equal to in this form and C is equal to this much. So, performing test at 2 different speeds N_1 and N_2 and diameter D_1 and D_2 we can obtain C and N .

(Refer Slide Time: 56:28)

- In taper turning, the speed at any given radius R or diameter D (Fig. 11) is

$$V = 2\pi RN = 2\pi N \left[R_1 + (R_2 - R_1) \frac{Nf}{L} T \right]$$
- $$V_{eq} = 2\pi N \left[\frac{1}{T_1} \int_0^T \left\{ R_1 + (R_2 - R_1) \frac{Nf}{L} T \right\}^{1/n} dT \right]^n \quad (16)$$
- Fraction of tool life consumed is:

$$X = \left(\frac{\pi N}{C} \right)^{1/n} \left(\frac{n}{n+1} \right) \left(\frac{L}{fN} \right) \left(\frac{R_2^{n+1} - R_1^{n+1}}{R_2 - R_1} \right) \quad (17)$$
- By performing two taper turning tests at spindle speeds N_1 and N_2 , the corresponding values of X_1 and X_2 can be obtained and n can be evaluated using equation





Fig. 12 Taper turning

In the same way, we can do taper turning also. In taper turning the tool is experiencing the variable speed because change of diameter. In this case, the equivalent speed expression becomes this and fraction of tool life consumed comes out to be like this. There is some algebra which I am skipping here. Now by performing 2 taper turning tests at spindle speeds N_1 and N_2 , the corresponding values of X_1 X_2 can be obtained and again you can obtain and N can be evaluated using that type of equation.

(Refer Slide Time: 57:04)



And so they have obtained that suppose, taper turning tests somebody obtained this type of curve and by conventional turning also the same type of curve similar type of thing was obtained.

(Refer Slide Time: 57:18)

- In *disc turning test* (Rao and Lal) proceeding in the same manner as for the facing test, the equivalent speed can be obtained as:

$$V_{eq} = \pi N \left[\frac{n}{n+1} \left(\frac{D_1^{\frac{1+n}{n}} - D_2^{\frac{1+n}{n}}}{D_1 - D_2} \right) \right]^n \quad (18)$$


- The fraction of tool life is:

$$X = \left(\frac{\pi N}{C} \right)^{\frac{1}{n}} \left[\frac{n}{n+1} \left(\frac{D_1^{\frac{1+n}{n}} - D_2^{\frac{1+n}{n}}}{2 f N} \right) \right] \quad (19)$$

- In these equations $D_1 > D_2$, being the outer diameter. In facing tests $D_2 > D_1$ since the tool moves outwards

In disc turning test, it is done the same way, but here we do the machining of a disc basically. So, we get this type of expression instead of we have disc not facing it is hollow type of disc that, we are basically machining. So, we are having this type of expression and fraction of tool life is this. So, in these equations D_1 is much is greater than D_2 and in facing test D_2 is greater than D_1 . Since the tool moves outwards, but in this one we are machining the basically the disc and from D_1 to D_2 ..

(Refer Slide Time: 58:11)



So that means, here we are doing turning disc is getting turned and then we can it can be obtained that here we get similar type of expression and we can also get this one.

(Refer Slide Time: 58:17)


MACHINABILITY

- The criterion used in these attempts could be classified into the following four broad categories:
 - (a) Tool-life criterion
 - (b) Production-rate criterion
 - (c) Power-consumption criterion
 - (d) Surface-finish criterion

Now, last point is that machinability. What do we call machinability? Criteria used in these attempts could be classified into the following 4 broad categories. Tool life criterion based on the tool life suppose tool life in machining a material is better then we can say the machinability of that material is better. Production rate criteria; if the production rate is high machinability is good, power consumption criterion; if power

consumption is less, then machinability is good. Surface finish criterion, if the surface finish is good we say machinability is good.

(Refer Slide Time: 58:54)



So, when tool life criterion is used it is common to express it in terms of cutting speed for a given tool life. We can have some reference. For example, if V_{TS} is the cutting speed for a tool life of T minute for this standard material and V_{TM} is the cutting speed for the same tool life for the test material then the machinability of the test material can be expressed as V_{TM} / V_{TS} into 100 percent. Suppose, the machine cutting is speed while machining material is same as the standard material, machinability is 100 percent. If the cutting speed much more, then the machinability is more than 100. So, like that otherwise it may be less than 100 percent.

So, these things are there. The expressions for variable tool life machining variable tool speed for finding out the cutting tool life ok, you can easily nicely do because there was lot of mathematics may be you might have faced some difficulty because, I have not derived very slowly, but this you if you see this book you can easily understand these expressions. In the book of GK Raman you can just do simple arithmetic and you can get to do that. So, I have told you today about the tool wear in which I have told that crater wear and flank wear is important and tool life also we discussed about tool life. Usually Taylor's tool life is very an imperial way to estimate the tool life and then I talk about then machinability of material.

Suppose, you can cut the brass very easily then it is called brass is a has got a good machinability. If you cannot cut some material very easily, it has got poor machinability. And machinability is can be accessed means cutting easily means the force should become should be less, surface finish should be good and tool wear should be less. So, any of these criteria or a combination of so, many criteria can be used and then you can define machinability. In fact, definition of machinability may vary from context to context and person to person. It is basically a subjective measure and this one. So, in the next class we will discuss some more interesting things.

Thank you.