


Computer Integrated Manufacturing
Professor. J. Ramkumar
Department of Mechanical Engineering and Design Program
Indian Institute of Technology, Kanpur
Lecture No. 22
CNC Part Programming (Part 4 of 4)

(Refer Slide Time: 00:20)




The next important topic in CNC is going to be, Manual Part Program, an Example. So, we will try to start from here, this is a component. So, we will try to start from point p0, then we go to p1. This is all in inches by the way; these are all in inches. So, we will go to p1, from p1 we will go to p2. You know the length; you know the angle which is set 45 degrees. Then from here you will try to come here offset. Then you have a radius, so the radius is divided into 2. So, this is one clockwise.

If you take it is as counter clockwise, counter clockwise and then this becomes your clockwise, whatever it is. So, you can try to do up to here and then you can try to split up to here. Or you can use the same command and then swing it up to here. p4, so this will be G00, this will be G01, this will be G01. This will be either G02 or 03, depending upon your requirement. And then, this is G01, and then G01.

So, if you wanted to do the component while machining, so here are the tools sizes given, feed rates, cutting speed, starting point, everything is given. So, this is speed 2 comma 2, this is what is given here. The program is in inches. So, we write p0, p1, p2, p3, p4, p5, p6,

p5 and p1, and then p0. So, if you want to make a component, so this is how a sequence has to be followed. Again here, you can choose either to do absolute or you can do incremental one.

(Refer Slide Time: 01:58)



So, let us do step by step, by step. First, set up the part programming. So, first block you write, N010. So, the entire program is inches, G70. We are going to follow absolute, G90. So here it says, the feed is in inches and then we have; this in inches. Then we have spindle speed in RPM, and then we will try to have spindle on, which is in the counter clockwise direction.

(Refer Slide Time: 02:30)

2. Set up the machining conditions

Machine moves in XY-plane
Use full-circle interpolation
Feed rate
Spindle speed

```
N020 G17 G75 F6.0 S300 T1001 M08
```

Tool no.
Flood coolant ON

So then, N02 I am trying to move. G17 is the plane, XY plane I am going to use. And then use, full circle interpolation is G75. Then we are defining the feed, cutting speed, tool number, and finally the flood coolant on. Miscellaneous will come at the last. This is second point.


(Refer Slide Time: 02:54)

3. Move tool from p0 to p1 in straight line

Linear interpolation
target coordinates

```
N030 G01 X3.875 Y3.698
```

$x = 4 - 0.125 = 3.875$
 $y = 4 - 0.125 \tan 22.5 = 3.698$



Then the third one is, we have N03. We are saying G01 X3.857 and Y is 3.698. So, this is the target coordinates, to the end point what it has to go. So now, from here it will try to go here. So, this is p1, this is p1. So, here if you look at it, so this is p1. So here, it is (4, 4), this point is (4, 4). So now, I have to go stop here. So, I have to find out the point. So, it is 4 minus 1.25 times, which is a diameter, so it is 3.85 comes here. And Y axis is this.

So, it is divided by tan 22.5, which is nothing but 44 divided by 2. So, it is 3.68. So, this will be my end points. So, from p0 I have to go towards the destination point of p1. So, this will be there. So, all the feeds and speeds we will take, this is the feed and this is the speed. And the tool 1, is used for the operation.

(Refer Slide Time: 04:02)

4. Cut profile from p1 to p2

Linear interpolation

target coordinates

```
N040 G01 X3.875 Y9.125
```

or

```
N040 G01 Y9.125
```

X-coordinate does not change → no need to program it

Manual Part Programming Ex.

Tool size = 0.25 inch,
Feed rate = 6 inch per minute,
Cutting speed = 300 rpm,
Tool start position: 2.0, 2.0
Programming in inches


Motion of tool:
p0 → p1 → p2 → p3 → p4 → p5 → p1 → p0

Next, from here I will try to do your linear interpolation, which will go from here N0, N40, G01. So now, from here I have to go up to here. So, what I will do is, I will try to; because this is 4 and this is 5, so this is 9 inches. So, I will have to go X3.875. I will go up to p2 destination which is 9.125. Why is this 125? because we have told the diameter of the cutter is 0.25 inches, so half of it.

I can write it like this. Since, there is no change in the X coordinate point, I can directly write G04, G01 and then I can say Y9.1. So, the X value is assumed to be the same. The X

coordinate does not change, so no need to change in the program. We are following absolute scale.

(Refer Slide Time: 05:02)




Then, from here I have to come up to here. So, this is what is N050 G01. I have to say from here it is 9.25, which is fixed. And from here, I know the diameter up to here; the length up to here is 2.5. And I have to, this radius is 1 inch. So now, I have to subtract it and find out what is p3, so p3 is a point here. So, we know the diameter is 0.25, so radius is 0.125.

So, this is your X axis, and this is your Y axis, and this is your X axis. So, X value will be 9. So, this will be the X value, it is 6.5 minus X to the whole square plus 0.125 to the whole square. This is going to be your X value. So, X is this. And 9, it is the same, so it is the 9.25 is there. So, this point is going to be (6.5, 9), this point. So, and then from here, we are going to draw a radius which is around about 1 inch. We will try to take this center and draw.


So currently, we are up to here. Then from here we have to move here, so that you can swing the radius to get it. So, here what they say is; they say that this total is 5 inches and then this is 2.5. So, this point plus 2.5 will try to give me the center. I have to find this point.

(Refer Slide Time: 06:36)




Next one is circular interpolation, counter clockwise motion. So, N60 G03. So, it is from here I have to swing it around up to here. So, it tries to tell me the point, so which is 7.366 and Y is along a straight line, 9.25. And I and J are the coordinates of the center of the circle, or you can try to define the radius of R. You can write it like this or you can write it like, N60 G03, X is the same, Y is the same. I0, you can define R0.8. Then you can go up to this point.

(Refer Slide Time: 07:15)




Then, from here we have to go along a straight line, so it is N70 G01. Now, I am not changing the Y value, it is only the X. I go to X9.302. So, the target value of Y is unchanged. So, it is linear interpolation. Here it was circular; counter clockwise circular, so here it is linear. So now, from here I will have to go again a linear towards the point p1.

(Refer Slide Time: 07:40)



So N080 G01. So, from here I am trying to go to this point which was 3.875, Y is 3.698. I come to this point p1.

(Refer Slide Time: 07:56)



And then, from here I will try to move here. So, it is G01. So, X2 and Y2; so, I come to this point and I say end of the data. And then I say, N100 M00 stop the program. So, the complete part is executed in this program. So, we have done it in 9 steps.

So, if you see this complete CNC program, we have done step by step, by step by, step. So, you will know p0, p1 how to go, p1, p2, p3, p4. Now interestingly, the latest software have come up in a great way. So, you do not have to do so much of small calculations, what is the offset. You just have to define these points, and the rest of the calculations will be done by interpolation techniques and the system takes care. So, you have to say p2, p3, p4, p5 and p1. So then rest of the calculations, it will take care. And then you can easily execute the program.

(Refer Slide Time: 08:55)

10. Complete RS-274 program

```
N010 G70 G90 G94 G97 M04  
N020 G17 G75 F6.0 S300 T1001 M08  
N030 G01 X3.875 Y3.698  
N040 G01 X3.875 Y9.125  
N050 G01 X5.634 Y9.125  
N060 G03 X7.366 Y9.125 R0.875  
N070 G01 X9.302  
N080 G01 X3.875 Y3.698  
N090 G01 X2.0 Y2.0 M30
```

N100 G00 X0 Y0

When I consolidately put this, complete program into number of blocks. So, this is how it looks like.

N010 G70 G90 G94 G97 M04

N020 G17 G75 F6.0 S300 T1001 M08

N030 G01 X3.875 Y3.698

N040 G01 X3.875 Y9.125

N050 G01 X5.634 Y9.125



N060 G03 X7.366 Y9.125 R0.875

N070 G01 X9.302

N080 G01 X3.875 Y3.698

N090 G01 X2.0 Y2.0 M30

(Refer Slide Time: 09:53)



So now, let us take; this is for your milling component. Now let us see, one example for a turning component. So, a simple G code example for a CNC lathe. As I told you, in milling you will have X, Y and Z; 3 points. But in that program, we did not have any Z value, because we assume the work piece to be a plate. So, it is a constant Z. So, that is why we did not define the Z value at all.

But now here, we can see how do we use the codes. So, in turning, we will have only 2 axes. One, this axis is called as the Z axis, and this axis is called as the X axis. If you look

at the complete component, the component has to be phased. And then it has to be turned. Then you will have a taper in the turning and then finally you make it.

So, the larger diameter is going to be dia80 and the smaller diameter is going to be dia50. The length of the shaft, whatever you have made, the length is going to be 30. And this length is going to be 50. So exactly dot, you can't keep the tool and start machining it because if there is any undulation on the work piece, the tool will get hit and the tool will get broken, the insert will get broken.

So, what we do, we always try to move it to a place which is little far off and safely keep at that point. So, here what we do is we try to keep it at a safer point. And from the safer point, we try to move it to the tip of the shaft. So, from here we go from A to B it goes. From B it goes to C, and from C it goes to D, and at D it tries to finish the component. So, we are going to write our CNC program accordingly.

We are not going into facing operation. This is only an example. So, we are supposed to know how to write the coordinates, along the given points A, B, C and D. So, it is very easy. So, from here to here, there is no variation in diameter, so it will be the same. Only variation is going to be the Z. So, here you will have X, as well as Z variation.

(Refer Slide Time: 12:10)

PART PROGRAM 2

Code Explanation

- N5 Clamping workpiece
- N10 Changing No.1 tool and executing its offset
- N15 Rapidly positioning to A point
- N20 Starting the spindle with 600 r/min
- N25 Cooling ON
- N30 Approaching B point with 600mm/min
- N40 Cutting from B point to C point
- N50 Cutting from C point to D point
- N60 Rapidly retracting to A point
- N70 Cancelling the tool offset
- N80 Stopping the spindle
- N90 Cooling OFF
- N100 Releasing workpiece
- N110 End of program, spindle stopping and Cooling OFF


So, let us see in words how are we going to write the code? and then we will see the code. So, N5 is clamping of the workpiece. Then N10, the changing number 1 tool and executing its offset because if the tool, whatever comes if you have to see what is; you have to call the tool and then you are to say all this offset. Every tool will have a register, in that register you will try to record all the details relevant to it. Then you will start moving it to position A, from somewhere you will start move it to position in A, in a very rapid speed.

Then, you start the spindle with 600 RPM. So, before machining, you will first start rotating the job and then only you will start are doing. When you start rotating the job, you will on for the coolant. Then once these 2; A position is reached, job started rotating, coolant start on then what will happen, the approaching point from A, you will move to approaching point B with 600 millimeter per minute. Because this happens in air, you are not touching the work piece. So, this happens in air, so you move in rapid speed.

Then cutting from B to C happens, at a given speed and feed rates. Then cutting from C, we go to D point. Then after finishing the D point, we retract the tool to come back to point A. Now, you should cancel the offset, whatever you are given, T01. Then you will stop the spindle, switch off the coolant, release the workpiece and then you say end of the program.

So, now we have described the complete sequence of operation for this particular program. So, I would give you as an assignment. Please start working on this assignment and you can submit it to us for correction.

(Refer Slide Time: 14:15)



So, let me see one more component. And this is milling a component. So, in this milling component, we have given you your home position here, this is the home position. We are trying to follow absolute. So, it is at this point where X is minus and Y is 86.95. From here we will use G00, come to here which is this point. So maybe, we might take this as 0 comma 0. So, this is A point which is 20 in X axis, Y axis it is 0. So, you can try to take this as 20 comma 0. From here you are going to this point, where we have given you the points 30.

So, this is 0 comma 30. And from here, you are going to this point wherein which, it is 10 offsetted from here and from here it is 100. So it is, X axis it is 10, X axis it is 30, and Y axis 100, this is the point. From here we are going to D. So D is going to be, this is 150. And here from 150, we are going to go up to here. So, this point E is 150, 150 minus 10, it is going to be in X axis 140. And this is going to be 60, so comma 60. So, from here we will go here.

So, from here to here, you have to use a circular interpolation. From here to here, you will use a linear interpolation. And from here to here, E we will be; Y axis will be 0. So, it is 150 plus 70, so it is (170, 0). And here naturally, so that I have missed out this 20 which is there from the origin. So, it is going to be (160, 60). So, let us see the sequence of operation, for this part you will write the program and you will submit.

(Refer Slide Time: 16:35)

CODE EXPLANATION

G90

N5 absolute positioning, metric unit
N10 tool change to T1
N15 define work zero point at A
N20 rapid traverse to A, spindle on (2500 RPM, CW)
N25 rapid plunge to 12.5 mm above Z0
N30 feed to Z-12.5, feed rate 150 MMPM
N35 cut line AB to B
N40 cut arc BC to C
N45 cut line CD to D
N50 cut arc DE to E
N55 cut line EA to A
N60 rapid retract to Z12.5
N65 reference point return in Z direction, spindle off
N70 reference point return in X and Y directions
N75 end of program

$Z = -12.5$

12.5

CNC MILLING EXAMPLE

Home position (-100, 86, 95)

G00

A(0,0) B(0,30) C(30,100) D(160,60) E(170,0)

80R 50R

150 70 30 10 10 10 10

So, when we try to look at the sequence, N5 absolute position, so G90 and metric units has to be used. Then you will have; next is call for tool 1. Then define work zero at A. So, if you want to define the point at A, you can make this as (0, 0) or you can try to make this point as (0, 0). I have made offset from this point as (0, 0) and I have given these values. But, if you want to follow the sequence what is given here, you can also do that.


So, define your work zero point at A. Then rapid traverse from a different coordinate system to A with a spindle speed on, this is what it is. Then at Z, you have to plunge 12.5.



So, Z will be throughout the program minus 12.5 because this is 0 of your workpiece, and this is 12.5. If you want to play safe, you can go even 16. So rapid plunge to 12.5 millimeter above 0. So now, the feed rate to Z -12.5 feed rate up to 150 millimeters per minute.

Now, cutline AB to B. Then from BC to C, CD to D, DE to E and EA to A. So, you are just going AB, BC, CD, and then you are going back to A, EA back to. So now, once you have finished all the cuts, now after reaching here you have to retrack that -12.5, 12.5 so it comes above. -12.50, 0, 12.5 it goes. So, then the reference point returns to Z direction, spindle is switched off, reference point returns to X and Y directions, and end of the program happens.

So, these are the sequence of operations. You just have to look into this program and then start writing. I have assumed this as my (0, 0) and I have given the point. But here, you please check whether they are talking the same. If it is same use it, if there is a change, from your understanding please make the changes accordingly and write a program.

(Refer Slide Time: 18:59)






Then let us look at one more program, sample program for drilling. So, you have; let us assume this is your 0 comma 0 and these are the points which we have given. And if you look at the slide view, it is not through hole drilling. The through hole of a plate will 0.5 but you are trying to run only 0.375. So, since it is a drill, you will always have this conical taper. So, you should have a flat. But since you are drilling and it is blind, you will have this depth; conical depth. So, the depth which is given here is 0.375. So, here it is inches.

So, please try to execute this program, the previous 2 and then this program, three programs and then you can share it across. Or if you have doubts, you can keep it for yourself.

(Refer Slide Time: 19:49)




Slide 1: Computer-Assisted Part Programming

• APT or Automatically Programmed Tool, is a high-level computer programming language most commonly used to generate instructions for numerically controlled machine tools.

• APT uses language statements to define part shape and tool motion as well as machine tool-dependent data (e.g., feed rates and spindle speeds). The general procedures of generating APT source codes involve the following steps:

1. Identify part geometry.
2. Identify cutter motions, feeds, speeds, and cutter parameters.
3. Code the geometry, cutter motions, and general machine instructions into the part programming languages. The code is known as source.



Slide 2: Computer-Assisted Part Programming

4. Compile or process the source to produce the machine-independent list of cutter movements and auxiliary machine control information, known as the cutter location data file (or CL data).
5. An APT processor program is used to read these statements, interpret the meanings, and perform all the necessary calculations to generate a series of cutter location points that define the toolpath.
6. The generalized APT output (usually in CL data) is converted to the particular format G-code required by the CNC machine using a post-processor program.
7. The CL data file contains (mainly) details of cutter moves, either as a series of absolute linear GOTO moves or relative GODLTA moves.

Now that we have understood manual programming, let us move to the next step called as computer assisted part programming. So, in computer assisted part programming, here it APT or Automatically Programmed Tools is high level computer programming language, most commonly used to generate instructions for numerical control machine tools.

APT uses language statements to define part shape and tool motions as well as machine tool dependent data example, feed rate, spindle speed. APT uses language statements to define part shape and tool motions, as well as machine tool dependent data. The general

procedure for generating APT source codes involves the following steps, identify the part geometry; identifying the cutter motion, feed, speed and the cutter parameters. Then we talk about the code, the geometric cutter motions and general machine instructions into a part programming languages. The code is known as a source code. We will see that.

Then it is moved to a compiler, a compiler or process the source to produce the machine independent list of cutter movements and auxiliary machine control information, known as cutter location data file, CL data file; Cutter Location. So, it compiles all the program and then it tries to take the cutter movement and the auxiliary machine control informations. An APT, processor program is used to read these statements, interpret the meanings, and perform all necessary calculations to generate a series of cutter location motion that define the tool path.

A generalized APT output usually is a CL, cutter location data is converted to the particular format G code, required by the CNC machine using a post processor program. Then CL data file contains details of the cutter movement, either as a series of absolute linear GOTO moves or relative GODLTA moves.

(Refer Slide Time: 22:23)


Computer-Assisted Part Programming

Note that the CL data is different from APT. The CL data is defined by the International Organization for Standardization (ISO).

- 7. Postprocess the CL Data to produce MCD for the particular target CNC machine.
- 8. Transmit the MCD to CNC machine and verify it.

Note that the CL data is different from APT. So, CL data is defined by the International Organization of Standards (ISO). And finally, you do post processing and transmitted to the MCD.


(Refer Slide Time: 22:37)



So, this is what a part programmer's job is, define path, define tool path operation, specify other functions speed, feed, etc. The computer's job will be, input translation, arithmetic and cutter offset compensation, editing phase and then it does a post processing. The

sequence of activities in computer assisted part programming is very important, you should understand.

(Refer Slide Time: 23:06)




The slide features a red header and footer. In the top left corner is a circular logo with the text 'APRIL 2015'. In the top right corner is a logo for 'IMAGINEERING LAB 3.107 KANPUR'. The main title is 'Automatically Programmed Tool' in bold red text. Below the title are three bullet points:

- A major advantage of APT is that it has developed into an accepted standard for machine tools, in addition to alleviating the burden of coding at the very basic level.
- A prime disadvantage of APT is that it uses English-like commands to define geometry instead of the much more convenient graphical methods.
- Note that the APT-type programming approach is being gradually replaced by the more advanced CAD/CAM approach.


Automatically programmed tools, a major advantage of APT is that it has developed into an acceptable standards for machine tools, in addition to the alleviating the burden of coding of very basic levels. The primary disadvantage of APT is that it uses English language command to define geometry instead of convenient graphical method. Note that, APT type programming approach is being gradually replaced by more advanced CAD/CAM approaches.


(Refer Slide Time: 23:45)



So in APT, suppose let us assume this is a part which has to be done and these are the points P1, P2, P3, P4, P5, P6, P7, P8 and P9. P1-P2 is joined together by a line L1. P2-P3, L2. P3-P4, L3. P4-P5, L4. P5-P6, L5. P6-P7, L6. P7-P8, L7. P8-P1, L8. So now, there are points P1 to P8 and there are lines which are L1 to L8. So, desired tool path and the geometry entities identified and labeled. This is a part and it is labeled.

(Refer Slide Time: 24:40)







So now, the APT source code is part number example. Machine was going to be Mill5; cutter is going to be of diameter D0. So now, what are you do is, you define all the points. Then you define all the lines, then you define your plane, what is the plane. And then you will say spindle on, feed rate, coolant. Then now, what you say is move from P0, GOTO L1 to plane 1 on L8. GOTO P0-P1; so it says GOTO L1 which is a line, to plane 1 on L8. So, you have to; this is meeting L8. So, you have to go to this point. From L8, there is a point coming, L1 there is a point coming and then we say GOTO point number P1.

Then you go left of L1 past L2; GOTO L1 past; so you are crossing L1. GOTO L1; go left of L1 and then you say past L2, up to L2. So, L2 you have to cross so that you go to this point, L2 this is what is L2. And then, you GOTO right of L2 to L3. Then go left of L3 past L4. Go right of L4 past L5. Go right of L5 to L6. Go left of L6 past L7. Go right L7 past L8. Go right of L8 past L1.



So, all these things will now, if you see closely watching, it will talk about how will the tool move to get to the profile. It will go left, go right L1, L2. You have defined all these M1. So here, you do not use any G-codes, M-codes, nothing. So, you try to use this English language and then you get. Then go rapid, it going out. Then go to point 0, coolant is off, end of program and then finish. So, this is just written in English.

(Refer Slide Time: 26:59)




Automatically Programmed Tool

- A major advantage of APT is that it has developed into an accepted standard for machine tools, in addition to alleviating the burden of coding at the very basic level.
- A prime disadvantage of APT is that it uses English-like commands to define geometry instead of the much more convenient graphical methods.
- Note that the APT-type programming approach is being gradually replaced by the more advanced CAD/CAM approach.




Computer-Assisted Part Programming


4. Compile or process the source to produce the machine-independent list of cutter movements and auxiliary machine control information, known as the cutter location data file (or CL data).
5. An APT processor program is used to read these statements, interpret the meanings, and perform all the necessary calculations to generate a series of cutter location points that define the toolpath.
6. The generalized APT output (usually in CL data) is converted to the particular format G-code required by the CNC machine using a post-processor program.
7. The CL data file contains (mainly) details of cutter moves, either as a series of absolute linear GOTO moves or relative GODLTA moves.



APT Source code




<p>PARTNO/EXAMPLE MACHIN/MILL5 CUTTER/0.75</p> <p>P0 = POINT/-1,-1,0 P1 = POINT/0,0,0 P2 = POINT/0,0,2,0,0 P3 = POINT/2,0,2,0,0 P4 = POINT/2,0,4,0,0 P5 = POINT/4,0,4,0,0 P6 = POINT/4,0,2,0,0 P7 = POINT/6,0,2,0,0 P8 = POINT/6,0,0,0</p> <p>L1 = LINE/P1, P2 L2 = LINE/P2, P3 L3 = LINE/P3, P4 L4 = LINE/P4, P5 L5 = LINE/P5, P6 L6 = LINE/P6, P7 L7 = LINE/P7, P8 L8 = LINE/P8, P1</p>	<p>PL1 = PLANE/0,0,-0.5,6,0,0,-0.5,0,2,0,-0.5</p> <p>SPINDL/2000</p> <p>FEDRAT/2.5</p> <p>COOLNT/ON</p> <p>FROM/P0</p> <p>GO/TO, L1, TO, PL1, ON, L8</p> <p>GOLFT/ L1, PAST, L2</p> <p>GORGT/ L2, TO, L3</p> <p>GOLFT/ L3, PAST, L4</p> <p>GORGT/ L4, PAST, L5</p> <p>GOLFT/ L5, TO, L6</p> <p>GOLFT/ L6, PAST, L7</p> <p>GORGT/ L7, PAST, L8</p> <p>GORGT/ L8, PAST, L1</p> <p>RAPID</p> <p>GOTO/ P0</p> <p>COOLNT/OFF</p> <p>END</p> <p>MHI</p>
---	---




Chang, 2003. Product Manufacturing and Cost Estimating using CAD/CAE. Elsevier Inc.

This is what we said here. So, here prime disadvantage of APT is that it uses English like command. So here, this also you should see. I told you. So, an APT post processor program is used to read these statements, interpret the meaning, and perform all the necessary calculations to generate a series of cutter location points. So, that is what is CL data file, which will be generated. So, this is the APT source code which is generated. This will be compiled and you can use it.


(Refer Slide Time: 27:34)



CAD/CAM Approach



- The CAD/CAM approach is the most popular and advanced approach in generating CNC codes.
- The process starts with creating a reference (or design) model and workpiece, and then assembling them in assembly mode.
- After the solid models are assembled, users define manufacturing set up, including choosing a workcell (e.g., a 3-axis mill) and coordinate system (or machine zero).
- Then, users create a machining sequence (e.g., a profile-milling sequence).

A presentation slide with a red header and footer. The title "CAD/CAM Approach" is centered in red. In the top left is a circular logo with the year "2015". In the top right is a logo for "IMAGINEERING LAB 1 IIT KANPUR" featuring a gear icon. The main content consists of two bullet points describing the CAD/CAM process.

CAD/CAM Approach


- In the meantime, users choose a cutter and specify machining parameters (e.g., federate, spindle speed).
- At this point, a machining sequence is completely defined. CAD/CAM will generate a toolpath; the toolpath was created using Pro/MFG for this example.

So, the next approach is going to be CAD/CAM approach. So, there will be a demonstration which will be done by Dr. Amandeep Singh, on this topic. But let us quickly go through what is covered here. The CAD/CAM approach is the most popular and advanced approach in generating CNC codes.

So here, manually we do not do it. We will read the drawing; the system itself will read the drawing. From the read drawing, it will try to understand. It will try to give you the G codes and M codes. The process starts with creating a reference model and work piece and then assembling them in an assembly mode. After the solid models are assembled, user defines the manufacturing setup, including choosing a work cell and the coordinate system. Then user creates some machining sequence depending upon the profile.

And in the meantime, user chooses a cutter and specify machining parameters. Then at this point, a machine sequence is completely defined. CAD/CAM will generator a tool path, and the tool path was created using Pro-e which is a commercially available software for this example.

(Refer Slide Time: 28:44)



The slide features a red header and footer. In the top left corner is a circular university logo. In the top right corner is a logo for 'IMAGINEERING LAB' with a gear icon. The main content is a bulleted list under the heading 'Summary'.

Summary

- How the programming works in NC machines?
- Various axial motions?
- Various types of Part programming?
- Various Preparatory and Miscellaneous codes used.
- How to do Manual part programming?
- What is Computer assisted programming?
- How to do Part programming using APT?
- CAD/CAM programming

To summarize, what all we saw in this lecture is, how the programming works in NC machine? What are all the various axial motions? What are the different types of part programming? Then various preparatory and G codes. How to use manual and part programming? What is computer assisted programming? How do part programming uses APT which is English based code, and CAD/CAM programming? Where we will see a simulation. Thank you.