

Theory of Production Processes
Dr. Pradeep Kumar Jha
Department of Mechanical Engineering
Indian Institute of Technology, Roorkee

Lecture – 17
Melting and Production of Iron Castings

Welcome to the lecture on melting and production of iron castings. So, in the last lecture we discussed about the furnaces which are required for melting of castings, specially either casting may be either of the non ferrous material or it may be of ferrous material, in ferrous you have either iron or sometimes you have steel. So, these are the two main components. So, iron means the variety of grey iron or cast iron. So, in that case basically the melting temperature is less than that of steel.

So, if you look at the iron carbon phase diagram, you will see that as the carbon composition increases carbon content increases towards the right, the melting temperature comes down. So, basically if you go to the eutectic point it comes close to 1140 degrees centigrade whereas, if you come to near the 0 degree 0 percent of carbon, it is close to 1540 degree centigrades.


So, there is lot of difference and the iron products like gray iron or white iron or S G iron or so, they are having variety of you know proper varied properties, because of which they are mostly used in many sectors like automobile construction or so. Although the cast iron has certain limitations also you I mean properties in certain way, but then there has been advances, there has been the advent of newer type of cast irons like gray cast iron or ductile iron or tempered ductile iron or so, which has made them very very popular material as a cast product, and used extensively specially in automobile industries.

So, as we discussed you have first of all this cast iron which is your important material, whose demand is quite high mostly if we look at the machine beds, where we have the component made of cast iron. In many cases the material is made of cast iron, if you go to any shop of machine shop or heavy machinery if you look at most of the structures which are the supporting they are normally made of this cast iron. The thing is that the cast ability being better and the easy casting the structure is higher.

So, that makes it and also the properties or so, good if you control the pressure parameters in a proper way in that case it is very much useful. So, that is why it is very important material and its demand is increasing day by day, and this is a very important type of material whereas, the properties of cast iron. So, as we know it has the some inferior properties as compared to steel specially when we check it against the tensile property, but its compressive property is quite high the damping property is quite good. So, machining property is quite good. So, these are the special properties for this cast iron.

Now, in the case of cast iron we define it. So, basically in the case of cast iron what we see you have the carbon percentage more than 2 percent will be there in the case of cast iron, then you have the silicon is present. So, basically silicon will try to stabilise the graphite because in normal case the carbon may go as carbide. So, because of the presence of silicon the carbon which is there that basically will be stabilised in the form of graphite. So, in the case of cast iron the carbon is normally in the case of in the form of graphite, also you will get carbide when the amount of silicon is less, or depending upon the cooling conditions either you can get the carbide or you can get the graphite now types of cast iron.

(Refer Slide Time: 04:50)




So, cast iron as we know cast iron one is gray cast iron. So, that is gray cast iron because the fracture surface is gray in colour. So, that is why it is gray cast iron, then you have

white cast iron. So, the white cast iron is its fractured surface is white. So, it is known as white cast iron.

Gray cast iron has very good compressive strength, less tensile strength little bit because of the presence of flaky graphite in the case of gray cast iron.

(Refer Slide Time: 05:20)



So, if you look at the gray cast iron, you will have the graphite flakes like this. So, so these are the flaky graphite in the case of gray cast iron. So, what happens this is soft. So, it gives a better damping properties, but these regions which have the pointed ends, they are the source the defect and they are the stress results. So, that is why in that in that tension state, it does not give very good property then you have another variety of cast iron is white cast iron.

So, the white cast iron in that basically the carbon is present in the form of Fe₃C combined carbon so, combined form. Now this is basically promoted because of the lower amount of silicon in the charge, and also because of the larger cooling rate. So, in the case of cast iron you need to maintain a slower cooling rate. Now cast iron in this case even the higher even with the higher silicon content or carbon content, if the cooling rate is fast in that case in certain area where the cooling rate is fast, you can have this structure of white cast iron or the hard phases formation that is carbide formation.

So, basically depending upon the percentage of silicon and carbon especially silicon because silicon is the graphitizer. So, silicon promotes the formation of graphite and also depending upon the cooling condition you get these white cast iron. So, because of the presence of the carbide iron carbide as carbon, also carbon is in the form of iron carbide this is very extremely hard. So, it does not much of the ductility, its very very hard and normally not used for nay engineering application, expect for the places where very high it can impart very high compressive stress, it can has it has very high extremely high hardness.

So, you are normally used for steel rolls in the steel rolling mills for rolls we use this material. But then this this cast iron is important because once we do the heat treatment of this cast iron the Fe_3C the carbon which is there in the Fe_3C this is decomposed. So, we if we subject it to annealing at a temperature of about 950 degree centigrade, and keep it for long duration then that is known annealing. So, it is done in the furnace at high temperature and then if this is maintained at that temperature for large amount of time, then basically disintegrates and it gives you free carbon. So, this Fe_3C breaks into Fe plus C . So, that is giving you free carbon or graphite. So, then that basically appears as small nodules nodules tempered for. So, this is known as temper carbon.

So, because of this annealing treatment, this carbon comes into this shape and then this is known as malleable iron. So, because of this annealing treatment for a prolonged duration, the hardness extreme hardness goes away, softness is induced and it has it develops a very high malleability and that is why it is known as malleable iron. So, it is very much used for the automobile components and it has very good formability and it is used for to mobile applications.

But nowadays, it is many at many places because it requires very large annealing treatment. So, energy consumption is quite high. So, even the SG iron is now a days preferred for making such components, which are required to be used in automobile applications. Next kind of iron I mean popular cast iron variety is the S G iron that is also known spheroidal graphite cast iron. So, this S G iron is basically the cast iron. So, in the case of white cast iron you get this cast iron by basically doing the heat treatment.

(Refer Slide Time: 10:35)




Whereas, a simply by casting, you can have the carbon as graphite nodules. So, these are nodules of the graphite.

Now, this is achieved by treatment the melt with either magnesium or cerium. So, if the cast iron melt is treated with magnesium or cerium, then what happens the first of all the sulphur content should be quite low. So, for that the Mg reacts with sulphur and Mg s as a slag is removed, and then the residual magnesium basically helps in changing the morphology of the graphite and it changes in such a manner that the growth of this graphite nodules is equal in all directions. So, it becomes a nodule here the growth is not in equal not equal in all the directions.

So, it becomes flaky type where as in this case because of the treatment with magnesium it becomes in nodular shape or spherical shape. So, that is how this kind of structure is obtained this is known as spheroidal graphite structure or nodular iron or ductile iron or so. So it has many name and this is known as this is the one variety which is very important variety. Apart from that you have mottled iron which is because of the freezing conditions if the part, part is freezing you know that is higher cooling part is at lower cooling rate in that case you will have the structure which is known as mottled iron. So, then you have ADI austempered ductile iron which is further treatment to ductile iron. So, what you get ADO. So, this way you have the different types of cast iron.

Now, you have the graphitization in cast iron as we discussed. So, graphitisation will be basically depending upon the percentage of carbon and silicon. So, as it will be more and also the cooling rate the cooling rate is small, then graphitisation will promote it otherwise not. So, these are the different parameters. So, solidification mechanism in cast iron, that we will discuss and these are typical microstructure in the cast iron that you get graphite, cementite, ferrite, pearlite, steadite austenite.

(Refer Slide Time: 13:16)




• **Solidification mechanism in cast iron**

- **Microstructure**
 - Graphite
 - Cementite
 - Ferrite
 - Pearlite
 - Steadite
 - Austenite

IT BOORKEE | NPTEL ONLINE CERTIFICATION COURSE 3

(Refer Slide Time: 13:18)




Metallurgy of Gray Iron

- Solidification of Fe-C-Si alloy system
- Graphitization during solidification and in solid state
- Chemical composition effects
- Types of graphite flakes

IT BOORKEE | NPTEL ONLINE CERTIFICATION COURSE 4

Now, we will discuss about the metallurgy of gray irons. So, how these solidification occurs in the iron carbon silicon alloy system, and then how the graphitization occurs and chemical composition effects and types of graphite flakes. So, let us see this is the you know iron carbide iron graphite equilibrium diagram.

(Refer Slide Time: 13:37)



So, if you look at this you can understand that how this solidification occurs wherever composition if we take.

So, once it comes to this temperature, then this is the liquidous line this side or this side and then once the solidification starts, once you come to this zone suppose it is hypo eutectic you know cast iron in that case here it will come. So, you will have one as here. So, austenite will be of this composition whereas, you will have. So, ultimately you have the liquid as well as the austenite. So, liquid will be there and austenite will be there, and then from here once it comes at this point. So, one will be following this line. So, one will be here and then another point will be here.

So, from here once it comes down this is the eutectic point. So, once you go below that you have if you look at this side you have the cementite. So, ultimately you will have the in this side you have cementite plus eutectic, in this side you have pro eutectic austenite plus. So, because the austenite is formed before the eutectic points, it is pro eutectic austenite plus eutectic ledeburite. So, that is here this point. So, in this zone we have pro


eutectic austenite plus eutectic ledeburite; ledeburite is the decomposition. So, that is what you get gamma plus cementite.

And as we come down to again this temperature so, further you have the conversion of this austenite, and then austenite will further change to the pearlite and cementite. So, you I hope that you are conversant with this iron carbon equilibrium diagram, which talks about the solidification mechanism, that as you come down at any place you have two basically two basic rules; one is the lever rule and is the tie line rule. So, that one talks about the amount of you know amount of liquid or solid which is there or two phase at any point, and then composition of the phases. So, amount will be basically done by this lever rule. So, that whoever it touches as per the lever rule, you are going to find the amount of the two phases, and then the tie line will talk about the composition.

So, as we see in this case what we see here that, once the silicon content is basically increases, in that case the you know this eutectic point is shifted towards left. So, that is basically known as the carbon equivalent value. So, in that case what happens that percentage carbon plus percentage silicon by 3, that talks about the carbon equivalence. So, if you have 3 percent of silicon and 3 percent of carbon that is basically carbon equivalent is 4 percent. So, that way it is or 3 percent of silicon and four 3 percent of carbon and 4 percent of silicon. So, that will reach at this 3 percent carbon itself you will have the eutectic point instead of 4.3 percent because 4 by 3 is 1.33.

So, that gives you 3 percent carbon itself will have the eutectic point. So, this is the point which should be kept in mind because the silicon is promoting the graphitization and it will basically shift this point towards the left side.

(Refer Slide Time: 17:44)



Now, this picture talks about the different kinds of you know graphite flakes distribution inside the matrix, and the type a graphite uniform distribution is the most preferred one, apart from that you have the different varieties different kinds in which the graphite may be distributed inside the domain, and this is type B is rosette type, type C is super imposed flakes, type 4 D and E they are inter dendritic segregation.

So, type a normally is the most preferred type of you know flake distribution, inside the matrix. Next we are going to study about the moulding related aspects of the casting of these iron based materials like gray cast iron or S G iron or even the white cast iron.

(Refer Slide Time: 18:37)

MOLDING

- Green sand molding most commonly practiced.
- Properties desired
 - Green compression & shear strength, dry compression strength, permeability, moisture content, etc.
 - When sand heated to ~1500°F, possibility of chemical reaction between sand & metal and adherence of fused on material on metal increases.
 - Sea coal, gilsonite, coke, graphite, pitch etc. may be added to sand for preventing the formation of fused products.
 - Grain size of 6, 12, 20, 30, 40 & 50 mesh (if > 75%, promote rough surface)
 - Excessive 270 mesh, fines, pan.....reduce ease of molding & permeability, increase expansion difficulties.

IIT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 7

So, for that green sand moulding is normally used, you require the green compression and shear strength, dry compression strength permeability moisture content, it is a adequate in the moulding material. The sand when it is heated to about 1500 degree Fahrenheit, then there is possibility of chemical reaction between sand and metal and there may be adherence of fused material on the you know metal.

So, you now you use sea coal gilsonite coke graphite pitch, it may be used in the sand for the prevention of the formation of these fused products, which are because of the reaction between the sand and the metal. Normally the grain size which is used is 6, 12, 30, 40 and 50 mesh. So, if you take more than 75 percent, then they promote the rough surface. Excessive two seventy mesh or fines as you know when the number I mean if the fine numbers mean higher fine mesh means higher numbers. So, if you take more then they reduce the ease of moulding and also permeability.

So, basically permeability is reduced because of the very fine particle; increase also expansion properties like the collapsibility is affected in that case then what are the foundry properties of the gray cast iron that we will discuss.

(Refer Slide Time: 20:24)

Foundry properties of Gray Iron

- Fluidity characteristics
- Shrinkage characteristics
- Relationship of gating design to
 - Pouring rate
 - Dirt prevention
 - Thermal gradient effects


IT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 8

(Refer Slide Time: 20:27)

Fluidity

$CF = \%C + (1/4 \%Si) + (1/2 \%P)$
(CF of 4.55 for maximum fluidity)

Fluidity (Inches) = $(14.9 \times CF) + 0.5T - 155$ (T = °F)



- Maximum fluidity occurs when pouring temperature is high & composition is eutectic one.
- Hypereutectic Gray Iron: Loss fluidity because of kishing, precipitation of carbon flakes as liquid metal cools.

IT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 9


So, fluid life that fluidity. So, fluidity is basically depending upon the percentage of carbon, silicon and phosphorous. So, phosphorous basically it gives the phosphorous and phosphor eutectic, because of that the fluidity also is increasing because of the presence of phosphorous. So, that is why phosphorous also comes into picture. So, if you carbon percentage silicon percentage and phosphorous percentage, then fluidity inches also fluidity will be affected because of this silicon and also the phosphorous content. So, that is why composition factor will be percentage carbon plus half 1 by 4 percentage silicon, plus half percentage phosphorous. And composition factor of 4.55 is said to have

maximum fluidity. So, once you have the composition factor known, you can have the fluidity inches according to this formula $14.9 \text{ into CF plus } 0.5 T \text{ minus } 155$. So, T will be at temperature affording in kelvin. So, in Fahrenheit.

Now the maximum fluidity is occurring when the pouring temperature is high and the composition is eutectic one, and hyper eutectic gray iron. So, for that basically there is loss of fluidity, because of the kishing of the or the precipitation of carbon flakes as liquid metal cools. So, in that case basically you know the flakes come up. So, that is how this fluidity is also you know affected, fluidity becomes less even for hyper eutectic type of gray iron.

So, for eutectic you will have maximum one, it will be less even for hypo eutectic side also for hyper eutectic side, because of the kishing effects.

(Refer Slide Time: 22:27)



Shrinkage Characteristics

- Solidification Shrinkage = $2(\% \text{ graphitic carbon} - 2.8)$
- ΔV (% volume change) may be +ve or -ve.
- (% Total Carbon = % Graphitic Carbon + % Combined Carbon)
- For ordinary Gray Iron (~2.9 to 3.1% graphite carbon), no risering is needed for the purpose of solidification shrinkage.
- If graphitization is complete, % of total carbon & % of graphite carbon are equal.

IT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 10


Shrinkage characteristics as we know in the case of gray cast iron, this is one of the advantage of cast iron that is since the graphite is transferred from carbon and this graphite has the lower density. So, basically there is expansion. So, shrinkage basically many times that is why it is very much good in castability because here that requirement arises many a times may be very very less. So, solidification shrinkage is normally two times percentage graphitic carbon minus 2.80.

So, ΔV it may be plus or positive or negative depending on percentage of graphitic carbon now. So, total graphite carbon will be I mean total carbon you can take it either as the graphitic carbon plus combined carbon. So, you have two types of carbon, one is carbon in the graphitic form and another is in the form of combined one. And if you have as you see from the figure if you have the shrinkage, if you have the graphitic carbon is more in that case if you look at Δv will be positive.

So, in that case you know no rising is needed. So, for 2.9 to 3.1 percent of graphitic carbon you do not have even the requirement of riser. So, that is how its shrinkage property is different than the other metals, where in most of the cases you have ΔV as negative change in volume is there if there will be shrinkage always, but in this case that is you have riser less type of solidification very much defined in the case of cast iron.

So, if though graphitisation as occurred percentage of graphite carbon is 0. So, that is how it is defined and depending upon that you will certainly you will have different kinds of micro structures.

(Refer Slide Time: 24:31)




- If no graphitization has occurred, % of graphitic carbon is zero.
- If about 0.5 to 0.8% combined carbon exists in Gray Iron, it generally indicates that microstructure is largely pearlitic.
- For white iron, ~5.6% shrinkage
- Riser presence, even required in case of gray iron as riser pressure gives rise to sound casting.

Now for white iron you have normally 5.6 percentage of shrinkage, because there is no graphitisation in that case where whereas, wherever there is graphitisation you will have less shrinkage or sometimes the shrinkage requirement is not to be when compensated by the riser.

So, further you have some times the pressure purging is there also in the pressure in the opposite side also. So, because of this pressure, because you know riser pressures even required in case of gray iron. So, riser pressure gives rise to a strong casting. So, that is also is there because of that you get the strong casting in quality of casting is better.

(Refer Slide Time: 25:25)



Inoculation


- Inoculation treatment is used to establish nucleation centres for precipitation of graphite into small type A flakes uniformly distributed in the matrix.
- Its advantage are:
 - Improved mechanical properties
 - Control of graphite structure
 - Elimination/reduction of iron carbide
 - Prevention/minimizing of undercooling¹⁸

IT KOOBEE | NPTEL ONLINE CERTIFICATION COURSE | 12

Inoculation treatment is normally used and this is used to establish the nucleation centre for the precipitation of graphite into small type a flakes uniformly distributed in the matrix.

So, normally the inoculation treatment is practiced. So, you have the inoculant, which go into the melt which is given into a melt. So, that you get a better flaky graphite structure a type of flaky graphite structure you are getting. And its advantage is that you have improved mechanical property, control of graphitic structure, elimination or reduction of iron carbide and prevention or minimising of under cooling. So, these are the you know advantage of inoculation.

(Refer Slide Time: 26:08)



Inoculation practice

- Inoculation in Ladle/ in mold
- Use of tablets, made by bonding powdered inoculant with wax or stearic acid
- A typical graphitizing inoculant has 72%Si, 1%Mn, 1% Ca, 2% Al and 4% Fe.
- In mold inoculation compensates for fading of primary inoculant, which might have occurred prior to pouring.

IT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 13

The practice is that, it is in the ladle or in the mould you can use you can use the tablets. So, which is made by bounding powdered, inoculant with wax or stearic acid and you have a typical graphitising inoculant used as 72 percent silicon 1 percent manganese, 1 percent calcium, 2 percent aluminium or 4 percent and 4 percent iron. So, normally these inoculants are used in the during the casting and it gives a better properties.

(Refer Slide Time: 26:42)



Heat Treatment of Gray Iron

Benefits:

- Improved machinability
- Wear resistance
- Strength
- Stress relief


IT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 14

Now, you also do the heat treatment of gray iron for improving its properties, like machinability wear resistance strength and stress relief.

(Refer Slide Time: 26:51)

Ductile Iron

- Advantage of Gray Iron (Low M.P., Good fluidity, excellent machinability, good wear resistance)
- Advantage of steel (High strength, Toughness, Ductility, hot workability and hardenability)
- Matrix of ductile iron can be controlled by base composition, by foundry practice and/or by heat treatment.



The image shows two circular micrographs side-by-side. The left one is labeled 'DUCTILE IRON' and shows a matrix with small, dark, spherical particles. The right one is labeled 'CAST IRON' and shows a matrix with larger, irregular, and more fragmented particles.

IT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 15

So, then another variety is the ductile iron. So, ductile iron as you know you the gray cast iron has certain disadvantages, that is basically compensated in the case of ductile iron, which is made by treating that material with the magnesium.

(Refer Slide Time: 27:17)


Solidification of ductile iron

- Solidification is at higher temperature as compared to Gray Iron.
- Magnesium/Cerium/Calcium and Yttrium are used for causing spheroids .
- Generally only 0.05% residual magnesium is necessary to achieve spheroid formation in most ductile irons.
- Nodule counts are directly affected by C content.

IT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 16

So, solidification is at higher temperature as compared to gray iron in this case, magnesium or cerium or calcium and Yttrium they are used for causing the spheroids, then you have only some amount magnesium is required to achieve this spheroid formation and nodule counts are directly affected by the carbon content.

(Refer Slide Time: 27:38)



➤ CE > 4.3 promotes development and growth of graphite spheroids.

➤ Si increases amount of ferrite formed during eutectoid transformation and strengthens iron by strengthening ferrite.

➤ S content after treatment ~ 0.015%


➤ P adversely affects toughness and ductility (a maximum of 0.05% is usually specified).

IF ROORKEE NPTEL ONLINE CERTIFICATION COURSE 17

Now, if the carbonic equivalent is more than 4.3 then it promotes the development and growth of the graphitic spheroids. So, you must see that this carbon equivalent should be more, for that you do a carbon and silicon content should be more.

now the sulphur content after the treatment has to be very very limited, because that affects because once there is sulphur the magnesium is mostly consumed, because of the this sulphur. So, sulphur is very much deleterious for this formation of nodular graphite, and p also is adversely affecting the toughness and ductility. So, you will have to limit the amount of p as well.

(Refer Slide Time: 28:24)



Melting

- Basic cupola preferred
- Acid melting cheaper, but not able to remove S easily.
- 0.01% S removal requires 0.1% Mg. Maximum fluidity occurs when pouring temperature is high & composition is eutectic one.
- Hypereutectic Gray Iron: Loss fluidity because of kishing, precipitation of carbon flakes as liquid metal cools.
- Mg first acts as deoxidizer and desulphurization. With residual Mg, graphite spheroids are formed.
- Mg is usually alloyed with other elements to increase its recovery (Mg-Ni alloy, Mg-FeSi alloy, Mg-Si alloy etc)

IIT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 18

For melting the basic cupola is preferred acid melting is cheaper, but now acid melting is not preferred because it will not be able to remove the sulphur, and sulphur is deleterious for this nodular iron.

So, you will have to see that you go for basic cupolas which is preferred; you know that when the sulphur is there and you put the magnesium first of all this magnesium is consumed by this sulphur. So, and also maximum fluidity is occurring when the pouring temperature is high, and the composition is eutectic one that is what we have seen when for the gray iron and you have some fluidity losses, because of the even hyper eutectic side. So, Mg will first act as deoxidiser and desulphurisation will take place. So, first of all it will react with sulphur and make the MgS, and with residual Mg itself graphite spheroids are formed. So, that is how you get and Mg which is used is normally as the ferro alloys like you have the different alloys. So, that is Mg nickel alloy or Mg Ferro silicon alloy or. So, so this way these are treated.

(Refer Slide Time: 29:43)

Methods of Mg treatment

- Open ladle method: Mg alloy kept at bottom of treatment ladle and metal poured over it.
- Sandwich method: Alloy is placed into a recession in the refractory bottom of ladle and covered by steel plate, iron chips, ferrosilicon or an inert material.
- Plunging method: Mg alloy placed into container positioned within a vented graphite or refractory bell fastened to a refractory covered plunging rod
- Mechanical Feeder

IT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 19

You have different methods of Mg treatment like you have ladle method sandwich method plunging method, and mechanical feeder and the purpose is that it will go into the melt and slowly it will go because it is explosive in nature. So, you have to put it there you have to have a sandwich type of method or you have in the corner you have somewhere slowly metal will go and it will react with that. So, that it does not create vigorous reaction with vigorous you know noise or so, and quietly it should mix. So, that one slowly it will go, and it will react and make the graphite spheroids.

(Refer Slide Time: 30:22)

Inoculation treatment

- Inoculation or post inoculation treatment is practice of making an addition to the melt which will increase the number of spheroids formed during solidification.
- Fe-Si alloy is the commonly used inoculant.
- Fe-Si alloy (0.5-1.5% Si) is added during inoculation.

IT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 20

You also do the inoculation treatment to increase the number of spheroids form during the solidification. So, ferrosilicon alloy is normally used as inoculant and ferrosilicon alloy that is 0.5 to 1.5 percent silicon is added during the inoculation, then you have also the foundry process controls.

(Refer Slide Time: 30:46)

Foundry process control

- Green/dry sand mold used
- Moisture content must be carefully controlled (because ductile iron, having been treated with Mg oxidizes easily).
- Pouring practice: pouring temperature more than 1420°C preferred), at low temperature (below 1380°C, oxidation products occur more readily).
- Mg addition increase surface tension compared with gray cast iron, hence sand mold is not easily wetted and burn in and penetration problems are avoided.

IT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 21

So, in that during the casting you as we have discussed you must have certain process control like you have to use the green or dry sand mould, in moisture content should be basically proper properly controlled, because the M g will oxidise easily then pouring practice. So, pouring temperature should be more than something like 1420 degree centigrade. So, that is proffered at low temperature the oxidisation products occurs more readily. So, that is the case in this melting of or production of nodular iron.

So, that needs to be seen then magnesium addition also increases the surface tension compared with gray cast iron. So, sand mold is not easily wetted and burning and penetration problems are avoided. So, this is the advantage in the case of casting of the nodular iron.

(Refer Slide Time: 31:45)




Heat Treatment of Ductile Iron

- Annealing (for good ductility and machinability)
(Holding at 900°C for 1 hour or more per inch of section thickness, cooling to 700°C and holding for 5 hours)
- Normalizing (for improvement in T.S.)
- Hardening and tempering
- Stress relief

IFT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 22

Then you have also the heat treatment of ductile iron, that is annealing is also carried out for good ductility and machinability. Normalising is done for improvement in tensile strength hardening tempering and stress relief is also carried out to improve the mechanical properties.

(Refer Slide Time: 32:02)



Malleable Iron


- Type of Iron with Graphite in the form of irregularly shaped nodules
- Produced by first casting the Iron as a White Iron, then heat treating to transform the Carbide into Graphite.
- Has considerable ductility and toughness due to the combination of nodular graphite and low carbon matrix.
- Matrix microstructure depends upon cooling rate.

IFT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 23

Another variety of cast iron is malleable iron where the curve the iron which has the graphite in the form of temper form, and it is a as we discussed it is formed y the heat


treatment of cast iron I mean in white cast iron that is annealing for a quite larger time, in the furnace itself which is increasing its ductility and toughness.

(Refer Slide Time: 32:30)



So, that is how you get the malleable iron this is the structure of malleable iron.

(Refer Slide Time: 32:31)



This is the annealing cycle of malleable iron which we get.

(Refer Slide Time: 32:38)

Steps in annealing

- First step: Nucleation of graphite
- Second step: Elimination of massive carbides (first stage graphitization)
- Third step: Slow cooling through allotropic transformation range (second stage graphitization), formation of completely ferritic matrix

IIT ROORKEE NPTEL ONLINE CERTIFICATION COURSE 26

And these are steps like in the first step there will be nucleation of graphite, second step you will have elimination of massive carbides, in the third step you have slow cooling through allotropic transformation range. So, this way what we see is that carbide structure is removed and you will have depending upon the situation either ferritic or paralytic matrix of.

Thank you very much.