


**Fundamentals of Materials Processing (Part-1)**  
**Professor Shashank Shekhar**  
**Department of Materials Science and Engineering**  
**Indian Institute of Technology, Kanpur**  
**Lecture Number 19**  
**Zone Refining (Continued)**

So we will continue our derivation for the relation for zone refining.

(Refer Slide Time: 00:20)



$$(C_0 - C_S) dx = dC_L \cdot dl$$

So here is the plot that we were discussing last time, and this was with respect to zone refining. So we saw that this is, we said this is a, we are assuming that this is the concentration of a crystal

that is shown over here. And then in zone refining, you are using the fact that the solute that forms during solidification has concentration less than that of the liquid. And so taking that concept further, what we do is solidification in a very limited zone; so this length we are looking at is only  $L$ . So this is a (different) zone which is in liquid state.  $L$  stands for the length here, and here this upper case  $L$  that I am writing is for the liquid state, this is solid state, and this is also in solid state.

So originally this solid overall had a concentration  $C_0$  like I have said here. And, when we do the solidification, then this, there is a curvature somewhere over here, curvature means there is a distribution, redistribution of the solutes, and the solute concentration has come down. So somewhere over here, let us say this is, this has this concentration, which we can say  $C_S$ , and taking the interface equilibrium, the corresponding concentration of liquid is  $C_L$ .

Now to find the relation for what will the plot look like, the new concentration plot will look like, what we will do is use a similar concept that we used for deriving Shell's equation; so this is the solute; let us say this is the additional amount of liquid that is solidifying. So this is the distance  $dx$  that has solidified, and therefore this amount of solute will get taken away from here; because you see the solute concentration was at this point earlier, and then after solidification, it will reach here.

So this is the solute concentration, or this is the total amount, not solute concentration, the total amount of solute that will be moved away. And where will it go? The liquid concentration will increase by a delta amount that is  $dC_L$ . So this liquid concentration has increased. So we will use this fact to set up the equation. So let us write down how the equation should look like.

(Refer Slide Time: 09:08)

$$(C_0 - C_s) dx = dC_L \cdot l$$


$$\frac{C_s}{C_L} = k \Rightarrow dC_L = \frac{1}{k} dC_s$$

$$(C_0 - C_s) dx = \frac{l}{k} dC_s$$

$$\frac{k dx}{l} = \frac{dC_s}{C_0 - C_s}$$

$$\left. \frac{kx}{l} \right|_0^x = -\ln(C_0 - C_s) \Big|_{C_0}^{kC_0}$$

$$-\frac{kx}{l} = \ln \left\{ \frac{(C_0 - C_s)}{(C_0 - kC_0)} \right\}$$



CS is a variable, CL is a variable, but they are related. So C0 minus CS times dx is this total amount of solute, and on the right side we RHS, we have dCL into (DL) into, not DL actually, it is L; dCL into L. So this is the dCL region, and this is the L region. So now we have a equation over here, and what we will do is we will also invoke the relation that CS by CL is equal to K implies dCL is equal to 1 over K dCS. And we will put replace dCL by this quantity 1 over dCS; so we will have a equation like this; or you can make it L over K dCS.

Now let us put K over L on this side times dx is equal to dCS by C0 minus CS. Now when we integrate it, this becomes Kx by L in a range; we will describe the range, and this becomes minus

In  $C_0$  minus  $CS$ , and the range. So what are the range?  $X$  moves from 0 to some value  $x$ . So this  $x$  goes from 0 to  $x$ . And in the same period, what happens to  $CS$ ? It moves from  $KC_0$ , you remember the first solid that forms is of concentration  $KC_0$ ; so it moves from concentration  $KC_0$  to some concentration  $CS$ .

Then we can take the minus sign over here; and I will not write any more over there, I will write the final equation that we should get over here, which will be. So, starting from this equation, if you solve it and using the limits that distance goes from 0 to  $x$ , concentration of  $CS$  goes from  $KC_0$  to  $CS$ ; this is the equation you will get or to simplify it further or to put it, put  $CS$  on the LHS, you will get  $CS$  equal to  $C_0$  minus. Now what do you see over here? We see that  $CS$  is equal to  $C_0$  minus some quantity; everything here is positive.

So the concentration of the solid part is less than  $C_0$ ; but it cannot of course happen throughout the length; but this equation from what we see, we see that it will happen throughout the length. That is because we have excluded the final transient zone. So let me to describe it, let me draw it, draw the plot in red. So, let us say this is during the process; after the process how would this plot look like? This would look like something like this. It is all less than  $C_0$ ; so see this is the concentration of solid starting from  $x$  equal to 0 to some value of  $x$ ; and if we go by this relation, it should keep going below  $C_0$ .

But, at some particular point, the concentration of the liquid will no more be  $C_0$ , or it will or basically there will not be enough liquid, and all the solutes will have reached that particular concentration. So, it will start to solidify over here; and this would probably be concentration  $C_E$ . So we are not talking of discs part in this equation; so this equation is limited only upto this point. So whenever we write a equation, you should also be aware of what are the limits, upto which it is being used and in this case this equation is being used only upto this point. And we can clearly see that the concentration of solid, the resolidified solid is lower than that of the original concentration.

Now this is just for one pass. Now let us say you get some another concentration or average concentration from this, which is obviously less than  $C_0$ . So next time you do it, you will get concentration even lower than that. So that way if you keep doing one pass, you reach  $C_0$  minus some  $\Delta C_1$  equal to  $C'$ . Second pass you may reach  $C'$  minus  $\Delta C_2$  equal to  $C$

double prime, and so on. So you see, if you keep increasing the number of passes, your concentration is decreasing far below the  $C_0$  value, and this is how you get the refinement or purification of the metal that you are using.

And the  $K$  value that we have used over here is if you, this over here we have assumed that it is complete diffusion, and there is no convection; but what we can also do is we can have some amount of convection in which case we will have to use the  $K$  effective value. And remember one thing that I did not explicitly mention about the  $K$  effective, but let me put it over here.

(Refer Slide Time: 12:08)



When you are growing a single crystal of limited length, then we know that, for only diffusion; when only diffusion is in place in the liquid, this is how the concentration profile looks like for the solid; and if you keep increasing the amount of convection, what happens to this plot; that should be where the  $K$  effective becomes very useful which I did not explicitly mention earlier, but let me show it now. I am drawing this Z kind of or this zigzag to show that the concentration increases sharply over there, and probably it is out of scale. If you increase the, if the  $K$  effective is even different, you may get something like this.

You may see that something, I am just putting some of the, of the tip of the tongue some values; these are not meant to be taken literally, these are just to give you an idea what may, what means when we are changing from complete diffusion to some amount of convection. So, let us say the  $K$  value, the actual  $K$  value was 0 point 3; when you have, very high amount of convection, the

K prime may reach equal to, K equal to 0 point 3. So if you depending on what is the K effective value, you may get different different kind of distribution or the solute concentration plot.

So this is again you can see one more thing from here regarding zone refinement, that when your original distribution is like this, and if you use the same condition, your new concentration will become smaller and smaller. So for example, this one was  $K C_0$ , this is  $K$  prime  $C_0$  for this  $K$  prime  $C_0$ , and your concentration gets the solute concentration in the solid becomes lower and lower. So that is all of the 'plane front solidification' in single phase alloy. Now what we will do is we will quickly take look at one example to get a better feel for this.

(Refer Slide Time: 12:35)

**Example Problem**

2

- A rod of Al-2% Cu alloy is normally solidified under the condition of no diffusion in solid and full mixing in liquid. It is given that melting temperature of Al is 660 C,  $T_E = 548$  C, maximum solubility of Cu in Al is  $C_{SM} = 5.65\%$  and Eutectic composition is  $C_E = 3.3\%$ . Assuming constant  $K$  over the temperature range of interest,

Draw the schematic of the effective solidus on phase diagram. Also draw the schematic of variation of  $C_s$ , solute composition, as a function of solidification length fraction  $f_s$ .

**Also obtain the values and show on the plot** important parameters ( $K C_0$ : the concentration of first formed solid,  $C_0$ : equilibrium concentration,  $f_s^*$ : fraction where concentration becomes larger than  $C_0$ ,  $f_s^E$ : fraction of length where concentration reaches  $C_{SM}$  and  $f_s^E$ : fraction where concentration reaches  $C_E$ ).

What fraction of the ingot is within  $\pm 5\%$  of the average composition


Dr. Shashank Shukla NPTEL-MOOC

So let us go to the slide, and what you see over here is a problem that is given with respect to 'plane front solidification'. What it says is that a rod of aluminium 2 percent copper; meaning aluminium is the main content, copper is your (concen) the added ingredient, so basically on the left side you will have aluminium, and you have added 2 percent copper alloy in is normally solidified under condition of no diffusion in solid, and full mixing in liquid. It is given that melting temperature of aluminium is 660 degrees celsius,  $T_E$  is equal to 548 C, maximum solubility of copper in aluminium is given, and eutectic composition is given.

So what you are given is that there is no diffusion in solid, and full mixing in liquid. So no diffusion in solid is something that we have always been considering, and the second condition it

says is that full mixing in liquid, meaning there is no concentration gradient in the liquid. So let us to get a feel of it, let us draw how this plot should look like.

(Refer Slide Time: 14:57)




So we are given some  $C_0$ , that  $C_0$  is 2 percent copper; so here you have aluminium,  $C_0$  is equal to 2 percent copper. You are given  $C_{SM}$ , you are given  $C_E$ . Now if you are given  $C_{SM}$  and  $C_E$ , you should be able to find  $K$ , which is the partition ratio. So we can get  $K$  equal to  $C_{SM}$  by  $C_E$ , which is 33, so it comes to 0 point 171. And, we also know  $C_0$ ; so  $C_0$  is 2 percent, so let us put it in fraction, so it becomes point 02, or if you put it or if you want to just use fraction percentage, that is also okay. So here we will be using percentage; so it becomes 0 point 171 into 2 is equal to 0 point 342.

So your  $KC_0$  value is this. And now let us look at what are the things that we need to find. So let us get back to the slide. Now these are the conditions that we are given, so we have plotted it, and now we have a feel of it. Now let us look at what the questions asks us to do. Draw the schematic of the effective solidus on phase diagram. Well we have already done that. Also draw the schematic of variation of  $C_S$ , solute composition as a function of solidification length fraction  $f_s$ . So this (was), this part is also easy.

Now what it asks, next part is the more important; also obtain the values and show on the plot important parameters,  $KC_0$ , the concentration of first formed solid is  $C_0$ , the equilibrium concentration, and there are different fractions it wants.  $f_1$ s, fraction where concentration

becomes larger than  $C_0$ ;  $f_2$ s, where fraction of length becomes, where concentration reaches CSM and it should be  $f_3$ s, fraction where concentration reaches CE. So, we need to find fractions, and put it on the concentration versus length plot.

(Refer Slide Time: 25:03)



So we will, this is how, first we will draw just in a schematic way how it should look like. This is; so this is fraction  $f$  equal to 1.  $C_0$  we know is equal to 2 percent; this is  $KC_0$ , which is equal to 0 point 342 percent. This is where what has been described as  $f_1$ . This is the point, this is  $f_1$  because it is at this point that the concentration of solute increases beyond  $C_0$ .  $f_2$  is the point where it reaches CSM. So this is CSM, which was given as 5 point 65. So we have to find a concentration for this. Then we have to also find the concentration where it reaches CE. So this is CE equal to 33 percent. So the fraction corresponding to this is  $f_3$ .

Now we have according to the question we have drawn the schematic for the phase diagram; we have drawn the schematic for the concentration profile. What we need to do now is just find values of  $f_1$ ,  $f_2$  and  $f_3$ . So let us start with  $f_1$ . What is the equation that we will use over here? We will use the Shell's equation; because it is the Shell's equation that is valid when you have no solid diffusion and complete homogenization in liquid. So let us write the equation which is.



(Refer Slide Time: 21:29)

0171  
0342

$$C_s = K G (1 - f_s)^{k-1}$$

$$G = K G (1 - f_s)^{k-1}$$

$$\frac{1}{K} = (1 - f_s)^{k-1}$$

$$1 - f_s = \left(\frac{1}{K}\right)^{\frac{1}{k-1}}$$


$$f_s = 1 - \left(\frac{1}{K}\right)^{\frac{1}{k-1}} = 0.881$$


$$G_M = K G (1 - f_s)^{k-1}$$

$$\left(\frac{G_M}{K G}\right) = (1 - f_s)^{k-1} \Rightarrow 1 - f_s = \left(\frac{G_M}{K G}\right)^{\frac{1}{k-1}}$$

$$f_s = 1 - \left(\frac{G_M}{K G}\right)^{\frac{1}{k-1}} = 0.966$$

~~$E = K G (1 - f_s)^{k-1}$~~





What we need here is  $f_s$ . We know CS for that particular  $f_s$ , and other values are constant. So for  $f_{s1}$ , what is CS? For  $f_{s1}$ , CS is equal to  $C_0$ . So we will put CS equal to  $C_0$ ; so we are trying to find  $f_{s1}$  over here; so this is  $C_0$ . And therefore, you can take, this becomes  $1$  over  $K$ . So you have to just put in the values, this is, and to be consistent let me put  $f_{s1}$  over here. So this, these are the  $f_{s1}$  values, and when you put in the  $K$  values, you would get  $0$  point  $881$ . So this is  $f_{s1}$ . Now next what we wanted is  $f_{s2}$ , the point where concentration reaches CSM. What is CSM? CSM is given as  $5$  point  $65$  percent.

So we will use again the same equation. Now instead of CS equal to  $C_0$ , we will put CS equal to CSM which is  $5$  point  $65$ ; so we will put like this. This is  $f_{s2}$ . So do not get confused that this is square, it is just a  $f_{s2}$ , superscript  $2$  represents the second fraction that we are trying to calculate here. So I will write over here. Now when you put the values, you would see that  $f_{s2}$  would come out equal to point  $966$ . So we have  $f_{s1}$ , we have  $f_{s2}$ , and these are the values. Now what about  $f_{s3}$ ? So do you think what we should also do the same thing. Now if we want to get the concentration  $f_{s3}$  for CSM should be put it like CE equal to  $KC_0$ . Is would that be the right way?

Well, we said earlier; there is a limit up to which this Shell's equation can be applied, and what is that limit? That limit is this point, the CSM value; because rest of it at that particular point in liquid state, and the point at that point in time, or the point in temperature when the solid reaches this concentration, the liquid reaches this concentration. So both of them solidify simultaneously, and therefore, what you see or the fraction at which you see CSM, it is the same fraction at

which the liquid solidifies, and therefore  $f_{s2}$  would be equal to  $f_{s3}$  and this equation is not valid for the, for finding the fraction at which concentration reaches CE.

And therefore, this equation or this plot, we can just simply now write the values;  $f_{s1}$  is point 881,  $f_{s2}$  is point 966 and  $f_s$  is equal to  $f_{s3}$ . So these are the different values of  $f_s$  and we have also solved it completely and we have found all the fractions that were needed. Now there is a still another part in the question which says “what fraction of the ingot is within plus minus 5 percent of the average concentration?” Which means, we have to find what is the delta  $f_s$  that lies. If this is  $C_0$ ; let me use a different chalk for this to emphasize. So we can say this is point 95  $C_0$ , and this is 1 point 05  $C_0$ .

So this question, this part of the question is saying, “what fraction of the overall solid lies within this composition?” Because overall composition was  $C_0$ ; so we want to know if some delta amount of fraction is lying within that  $C_0$  fraction, and what is that, what is that delta amount of the length of the fraction. So, here is your  $C_0$ , and this is the solute concentration, which is continuously changing. Therefore what we need to find here is, this  $f_s$  and this  $f_s$ . Let us call it  $f_s$  prime, and let us call it  $f_s$  double prime. And, what is the concentration at  $f_s$  prime? The concentration at  $f_s$  prime is point 95  $C_0$ ; the concentration at  $f_s$  double prime is 1 point 05  $C_0$ .

(Refer Slide Time: 27:16)

Handwritten mathematical derivations on a chalkboard:

$$1.05 \times C_0 = K C_0 (1 - f_s) \Rightarrow \left(\frac{1.05}{K}\right)^{\frac{1}{1-k}} = 1 - f_s \Rightarrow f_s = 1 - \left(\frac{1.05}{K}\right)^{\frac{1}{1-k}} = 0.888$$

$$\left(\frac{0.95}{K}\right)^{\frac{1}{1-k}} = 1 - f'_s \Rightarrow f'_s = 1 - \left(\frac{0.95}{K}\right)^{\frac{1}{1-k}} = 0.874$$

$$\Delta f_s = f_s - f'_s = 0.014$$

The value 0.014 is boxed and labeled as 1.4%.

So, let us again use Shell's equation. So; this is  $f_s$  prime, or sorry we have put 1 point 05; so it is  $f_s$  double prime. So this is the relation to get you  $f_s$  double prime, and you can get the value of  $f_s$  double prime as. Now similarly, instead of 1 point 05, we could have put point 95; and we will get a value of point  $f_s$  prime, which is equal to point 874. So the difference between these two is the fraction that lies within this. Fraction-wise, it is 0 point 014, which means 1 point 4 percent of the crystal that has solidified lies within plus minus 5 percent of the overall alloy composition  $C_0$ .

So you see, it is a very very small fraction that lies within this  $C_0$  value. So this is a very interesting information that although the overall composition is  $C_0$ , but the composition which lies within this plus minus 5 percent of the overall composition is a very small fraction; most of it lies outside. And in fact, most of it lies below it, and beyond this  $f_s$ , the value that we found over here, point 966, you see values higher than CSM. So at that point, you are getting something like a eutectic.

So this is again another important aspect is, that point 966 is the value at which you reached point the CSM, or the solute concentration at the left most point of the liquidus, sorry left most point of the eutectic, and that is also the point where you reached, the liquid reached the eutectic; so around point 034 fraction of the solid has eutectic composition, which means that you have a very even in this very very small composition, you are able to reach the eutectic composition.

So, that is again to show that even though you may have a single phase alloy with very very minor concentration of the solute, you may still reach a eutectic composition and a two phase region. So with that we will end today's lecture and we will come back into the next lecture with the second part, which is a cellular solidification. So this was all we had about the planar solidification in single phase alloy; now next we will get into cellular solidification of single phase alloys. We are still with the single phase alloys, but for the cellular solidification. See you in the next lecture.