# PSG COLLEGE OF ARTS & SCIENCE

(AUTONOMOUS)

### **BCom DEGREE EXAMINATION DECEMBER 2017**

(Sixth Semester)

## **Branch- COMMERCE (BUSINESS PROCESS SERVICES)**

#### **MANAGING BUSINESS PROCESSES - II**

Time: Three Hours Maximum: 75 Marks

## **SECTION-A (20 Marks)**

Answer **ALL** questions

ALL questions carry EQUAL marks  $(10 \times 2 = 20)$ 

- 1 Define quality.
- What is a control chart?
- What is a defect?
- 4 What is process flow diagram?
- 5 What do you mean by pare to charts?
- 6 What is Histogram?
- What is lean tool?
- 8 What is push system?
- 9 What is quality management?
- 10 Define six sigma.

## **SECTION - B (25 Marks)**

Answer **ALL** Questions

**ALL** Questions Carry **EQUAL** Marks  $(5 \times 5 = 25)$ 

11 a What are the objectives of why analysis?

OR

b State the stages involved in failure mode and effect analysis.

12 a List out the steps involved in constructing a pare to chart.

 $\bigcap R$ 

b How can you construct Histogram?

13 a Explain the workings of six sigma.

 $\cap R$ 

b Narrate the ingredients of six sigma Programme.

14 a What are the principles of lean

OR

b Distinguish between pull system and push system.

15 a What are the fundamental principles of quality management.

OR

b Examine the uses of password and identity management.

#### **SECTION - C (30 Marks)**

Answer any **THREE** Questions

ALL Questions Carry EQUAL Marks  $(3 \times 10 = 30)$ 

- Narrate the benefits of failure mode and effect analysis.
- 17 State the different types of control charts for attributes.
- Describe the project methodology of six sigma.
- 19 Analyse the 55 principles of learn management.
- What are the risks involved in quality management.

Z-Z-Z END